AGENDA

MATANUSKA-SUSITNA BOROUGH

350 East Dahlia Avenue, Palmer, Alaska 99645 – 907-861-7874

PLATTING OFFICER Fred Wagner

PLATTING ADMINISTRATIVE SPECIALIST Kayla Kinneen



PLATTING TECHNICIANS
Matthew Goddard
Chris Curlin
Wyatt Anderson

PLATTING ASSISTANT Connor Herren

ABBREVIATED PLAT AGENDA ASSEMBLY CHAMBERS 350 EAST DAHLIA AVENUE, PALMER

REGULAR MEETING

8:30 A.M.

February 19, 2025

Public Participation: To participate in the Abbreviated Plat Hearing, you can attend in person, or you can submit written comments by email to platting@matsugov.us or by mail to Matanuska-Susitna Borough, Platting Division, 350 E. Dahlia Avenue, Palmer, AK 99645.

1. INTRODUCTION

A. Introduction of Staff

2. UNFINISHED BUSINESS:

(None)

3. PUBLIC HEARINGS:

- A. MEADOW LAKES TOWN CENTER RSB B3 L7: The request is to create 2 lots from Block 3, Lot 7 of, Meadow Lakes Town Center Phase 1 Subdivision, Plat No. 2010-73, (Tax ID #6990B03L007) to be known as MEADOW LKS TWN CTR RSB B/3 L/7, containing 12.57 acres +/-. The plat is located directly North of W. Marigold Drive, East of W. Parks Highway, and directly West of S. Sylvan Road; located within the NE ½ Section 09, Township 17 North, Range 02 West, Seward Meridian, Alaska. In the Meadow Lakes Community Council and in Assembly District #7. (Petitioner/Owner: Meadow Lakes Investment, LLC, Staff: Wyatt Anderson, Case #2025-011)
- B. **DAKOTA RIDGE:** The request is to create four lots from Lot 1, Brendon Woods (Plat # 2021-99), to be known as **DAKOTA RIDGE**, containing 10.76 acres +/. The property is located directly north of E. Huntley Road and east of N. Koppenburg Road; (Tax ID 8169000L001); within Section 25, Township 18 North, Range 02 East, Seward Meridian, Alaska. In the Lazy Mountain Community Council and Assembly District #1. (Petitioner/Owner: John Harmon, Staff: Chris Curlin, Case #2025-013)

- C. <u>SCORPION</u>: The request is to create two lots from Lot 1A, McCallister Subdivision, Plat No. 2014-11 to be known as **SCORPION**, containing 4.3 acres +/-. The property is located north of the Alaska Railroad, east of N. Stanley Road, and directly south of W. Parks Highway (Tax ID # 7267B01L001A); within the NW ½ Section 07, Township 17 North, Range 01 West, Seward Meridian, Alaska. In the Meadow Lakes Community Council and in Assembly District #7. (Petitioner/Owner: Dan Hacker & McCallister Investment Group, LLC, Staff: Matthew Goddard, Case #2025-014)
- D. **ROWLAND FOREST RSB L4-5:** The request is to create two lots by adjusting the common lot line between Lots 4 & 5, Rowland Forest Subdivision, Plat No. 2019-20 to be known as **Lots 4A & 5A**, containing 6.76 acres +/-. The property is located west of N. Tranquility Lane, east of N. Smith Road, & north of E. Maud Road (Tax ID # 7837000L004 / L005); within the SW ½ Section 01, Township 17 North, Range 02 East, Seward Meridian, Alaska. In the Butte Community Council and in Assembly District #1. (Petitioner/Owner: Rowland Properties, LLC, Staff: Matthew Goddard, Case #2025-015)

THE ABBREVIATED PLAT HEARING WILL CONVENE AT <u>8:30 A.M</u> on <u>February 19, 2025</u>, in the <u>ASSEMBLY CHAMBERS</u> at the Dorothy Swanda Jones Building, 350 E. Dahlia Avenue, Palmer, Alaska.

Public Hearing Process

- > Platting Officer states/reads the case/item to be addressed into the record.
- **Public Hearing Notices**: Secretary states the number of public hearing notices sent out and the date sent.
- > Staff Report: The Platting Officer gives an overview of the project for the hearing and the public.
- **Public Testimony**: Members of the public are invited to sign in and testify before the officer.
 - o 3-minute time limit per person for members of the public.
 - The time limit may be extended at the discretion of the Platting Officer.
- The public hearing is closed by the Officer. No further public input is appropriate.
- **Petitioner Comments**: Petitioner, or his/her representative, comes before the officer to discuss staff recommendations and compliance with Title 43 and other applicable regulations.
 - o Testimony is limited to five (5) minutes for the petitioner/applicant.
 - o The time limit may be extended at the discretion of the Platting Officer
- ➤ Motion to Approve: Motion to approve is made by the Platting Officer.
 - o No further unsolicited input from petitioner is appropriate.
 - o Conditions and Findings must be written for all decisions made regarding the action being taken, whether it passed or failed.
 - o Decisions are final unless reconsidered by the platting board MSB 43.35.005 or appealed to the board of adjustments and appeals. MSB 43.35.015

STAFF REVIEW AND RECOMMENDATIONS PUBLIC HEARING FEBRUARY 19, 2025

ABBREVIATED PLAT: MEADOW LKS TWN CTR RSB B/3 L/7

LEGAL DESCRIPTION: SEC 09, T17N, R02W, SEWARD MERIDIAN AK

PETITIONERS: MEADOW LAKES INVESTMENT, LLC.

SURVEYOR/ENGINEER: THE BOUTET CO., TRIAD ENGINEERING

ACRES: $12.57 \pm PARCELS: 2$

REVIEWED BY: WYATT ANDERSON CASE #: 2025-011

REQUEST: The request is to create 2 lots from Block 3, Lot 7 of, Meadow Lakes Town Center Phase 1 Subdivision, Plat No. 2010-73, to be known as MEADOW LKS TWN CTR RSB B/3 L/7, containing 12.57 acres +/-. The plat is located directly North of W. Marigold Drive, East of W. Parks Highway, and directly West of S. Sylvan Road; located within the NE ¼ Section 09, Township 17 North, Range 02 West, Seward Meridian, Alaska. In the Meadow lakes Community Council and Assembly District #7.

EXHIBITS

Vicinity Map and Aerial Photos	EXHIBIT A $-$ 5 pgs
Soils Report	EXHIBIT B – 4 pgs
AGENCY COMMENTS	10
Department of Public Works	EXHIBIT C – 1 pg
Permit Center	EXHIBIT D – 1 pg
ADOT	EXHIBIT E – 2 pgs
Utilities	EXHIBIT F – 2 pgs

<u>DISCUSSION</u>: The proposed subdivision is creating two lots. Lot 7A is 7.56 acres and Lot 7B is 5.00 acres. Access for Lot 7A is W. Marigold Drive, and access for Lot 7B is S. Sylvan Road. W. Marigold Drive and S. Sylvan Road are both Mat-Su Borough owned and maintained roads.

Soils Report: A geotechnical report was submitted (Exhibit B), pursuant to MSB 43.20.281(A). Grant Mathews PE, notes that Triad Engineering, LLC performed a soils investigation on November 25, 2024. A test hole was excavated at the location shown on the map. Soils encountered during the investigation were visually classified in general accordance with the Unified Soil Classification System (USCS). The general subsurface profile encountered for Lot 7B consisted of well graded sands and gravels (SW/GW) from the surface down to bottom of the test hole, at 12 feet. Based on the soils encountered, no confirmation percolation testing was warranted. Perc rates less than 1 min/inch are anticipated based on the visual classification of the soils. No groundwater or weeps in the trench sidewalls were encountered during the excavation. A test hole log is attached with this report. Based on field observations and review of the existing topography, adjacent properties, and site conditions, the proposed Lots 7A & 7B have at least

10,000 square feet of usable building area and 10,000 square feet of contiguous usable area for a septic drain field in accordance with the MSB Title 43 Code, section 43,20,281.

Comments: Department of Public Works (Exhibit C) has no comments.

Permit Center (Exhibit D) has no comments.

ADOT (Exhibit E) has no objections.

<u>Utilities</u>: (Exhibit F) Enstar has no comments, recommendations or objections. MTA commented, "MTA has existing facilities placed jointly with MEA on lot 7 of plat 2010-73. We will be reaching out to the land owner for our own easement.". MEA did not respond.

At the time of staff report write-up, there were no responses to the Request for Comments from USACE; ADF&G, U.S. Postmaster, Meadow Lakes Community Council; Fire Service Area #136 West Lakes; Road Service Area #027 Meadow Lakes; Assembly District #007, MSB Community Development, Emergency Services, Assessments, Planning Division, or Development Services; or MEA.


<u>CONCLUSION</u>: The abbreviated plat of Meadow Lks Twn Ctr Rsb B/3 L/7 is consistent with AS 29.40.070 Platting Regulations and MSB 43.15.025 Abbreviated Plats. There were no objections from any federal or state agencies, Borough departments, or utilities. There were no objections to the plat from the public in response to the Notice of Public Hearing. Legal and physical access exists to the proposed lots, consistent with MSB 43.20.100 Access Required, MSB 43.20.120 Legal Access and MSB 43.20.140 Physical Access. Frontage for the subdivision exists, pursuant to MSB 43.20.320 Frontage. A soils report was submitted, pursuant to MSB 43.20.281(A)(1).


FINDINGS OF FACT

- 1. The plat of Meadow Lks Twn Ctr Rsb B/3 L/7 is consistent with AS 29.40.070 Platting Regulations and MSB 43.15.025 Abbreviated Plats.
- 2. A soils report was submitted, pursuant to MSB 43,20.281(A)(1).
- 3. All lots will have legal and physical access consistent with MSB 43.20.100, MSB 43.20.120 and MSB 43.20.140.
- 4. Each lot has the required frontage pursuant to MSB 43.20.320.
- 5. At the time of staff report write-up, there were no responses to the Request for Comments from USACE; ADF&G, U.S. Postmaster, Meadow Lakes Community Council; Fire Service Area #136 West Lakes; Road Service Area #027 Meadow Lakes; Assembly District #007, MSB Community Development, Emergency Services, Assessments, Planning Division, or Development Services; or MEA.
- 6. There were no objections from any federal or state agencies, or Borough departments.
- 7. There were no objections from the public in response to the Notice of Public Hearing.


<u>RECOMMENDATIONS OF CONDITIONS OF APPROVAL</u> for the abbreviated plat of Meadow Lks Twn Ctr Rsb B/3 L/7, Section 09, Township 17 North, Range 02 West, Seward Meridian, Alaska, contingent on staff recommendations:

- 1. Taxes and special assessments must be paid in full for the year of recording, pursuant to MSB 43.15.053(F) and AS 40.15.020. Pay taxes and special assessments (LIDs), by CERTIFIED FUNDS OR CASH.
- 2. Provide updated Certificate to Plat executed within seven (7) days of recording of plat and submit Beneficiary Affidavit for any holders of a beneficial interest.
- 3. Pay postage and advertising fees.
- 4. Show all easements of record on final plat.
- 5. Submit recording fees, payable to Department of Natural Resources (DNR).
- 6. Submit final plat in full compliance with Title 43.









W E





ENGINEERING. LLC

PHYSICAL

MAILING

OFFICE

WEB

615 E. 82nd Ave., Suite 101

Anchorage, AK 99518

P.O. Box 111989

Anchorage, AK 99511

907-561-6537

triadak.com

January 14th, 2025

Mat-Su Borough Planning Department 350 E. Dahlia Ave.

Palmer, AK 99645

Attention: Fred Wagner, PLS

Subject:

Meadow Lakes Town Center, Lots 7A & &B

Usable Area Report

RECEIVED

JAN 1 4 2025

PLATTING

Mr. Wagner,

This letter provides a usable area analysis for proposed Lots 7A & 7B, Meadow Lakes Town Center in accordance with the Mat-Su Borough (MSB) Title 43 Code Requirements.

Project Description

The project site consists of an existing 12.6-acre parcel identified as Lot 7, Block 3, Meadow Lakes Town Center, Phase 1 Subdivision. The parcel is located in Meadow Lakes at the northwest quadrant of the intersection of W Marigold Dr and Sylvan Rd. The property contains two metal warehouse buildings, associated parking, and a well and septic system. The proposed plat will subdivide the parcel into two lots, creating a 5-acre parcel along Sylvan Rd out of an area that is currently a graded, gravel pad but otherwise undeveloped.

Soils Investigation


Triad Engineering, LLC performed a soils investigation on November 25th, 2024. Dirtworks, Inc mobilized a Hitachi 135 excavator to the site and provided an operator for the investigation. A test hole was excavated at the location shown in the map on the following page.

Soils encountered during the investigation were visually classified in general accordance with the Unified Soil Classification System (USCS). The general subsurface profile encountered for Lot 7B consisted of well graded sands and gravels (SW/GW) from the surface down to bottom of the test hole at 12 feet. Based on the soils encountered, no confirmation percolation testing was warranted. Perc rates less than 1 min/inch are anticipated based on the visual classification of the soils. No groundwater or weeps in the trench sidewalls were encountered during the excavation. A test hole log is attached with this report.

January 14th, 2025

Subject: Meadow Lakes Town Center Lots 7A & 7B

Usable Area Report Page 2 of 2



Location Map

Useable Area

Based on field observations and review of the existing topography, adjacent properties, and site conditions, the proposed Lots 7A & 7B have at least 10,000 square feet of usable building area and 10,000 square feet of contiguous usable area for a septic drain field in accordance with the MSB Title 43 Code, section 43.20.281.

The existing well and septic system on Lot 7A will continue to serve the warehouse buildings.

Thank you for your time and consideration in this matter. If you require additional information, please call 907-644-3981 or email me at grantmathews@triadak.com.

Sincerely,

TRIAD ENGINEERING, LLC

Grant Mathews, P.E.

Attachments: Excavation photo

Test Hole log






Municipality of Anchorage

Development Services Department
On-Site Water and Wastewater Section
4700 Elmore St.
P.O. Box 196650 Anchorage, AK 99519-6650
www.muni.org/onsite
(907) 343-7904



Soils Log - Percolation Test

Pe	erformed	For: Mark Lars	on - Keyst	one Holding	S	Date Performed	11.25.24			
Leg	al Descr	iption: Meadow Lakes Tov	vn Center Lot 7	enter Lot 7B Township, Ran			ge, Section:			
	Slope			Slope	Site Plan					
	Depth									
	(Feet)									
1-										
2-										
3-		Clean Sand & Gravel								
4-		SW/GW								
5-										
6-										
7-										
8-										
9-			WAS GROUN ENCOUNT							
10-		1	IF YES, AT WH	IAT DEPTH?	s L					
11-			Depth to Water After Monitoring? N/A							
12-		BOH @ 12'		Date: 11.2	E					
13-		2011 @ 12								
14-			Reading	Date	Gross Time	Net Time	Depth to Water	Net Drop		
15-										
16-										
17-										
18-										
19-										
20-										
		ı								
		PERCOLATION RATE (minutes/inch)			PERC HOLE DIAMETER					
TEST RUN BETWEEN FTAND FT COMMENTS No perc test completed. Anticipated perc rate <1 min/inch based on visual observations.										
PERFORMED BY: Triad Engineering, LLC Grant Mathews CERTIFY THAT THIS TEST WAS										



Wyatt Anderson

From:

Pre-Design & Engineering

Sent:

Tuesday, February 4, 2025 3:09 PM

To:

Wyatt Anderson

Cc:

Brad Sworts; Jamie Taylor; Tammy Simmons; Daniel Dahms

Subject:

RE: Meadow Lakes Town Center RSB B/3 L/7

Wyatt,

No comments from PD&E.

PD&E

From: Wyatt Anderson < Wyatt. Anderson@matsugov.us>

Sent: Tuesday, January 21, 2025 1:08 PM

To: kristina.huling@alaska.gov; erica.kostelecky@alaska.gov; david.post@alaska.gov; colton.percy@alaska.gov; sarah.myers@alaska.gov; tim.swezey@mlccak.org; psfisherak49@gmail.com; information@mlccak.org; camden.yehle@mlccak.org; mschoming@crweng.com; Tawnya Hightower <Tawnya.Hightower@matsugov.us>; Brian Davis <Brian.Davis@matsugov.us>; Land Management <Land.Management@matsugov.us>; Jillian Morrissey <Jillian.Morrissey@matsugov.us>; Tom Adams <Tom.Adams@matsugov.us>; Brad Sworts <Brad.Sworts@matsugov.us>; Jamie Taylor@matsugov.us>; Daniel Dahms <Daniel.Dahms@matsugov.us>; Tammy Simmons <Tammy.Simmons@matsugov.us>; Christina Sands <Christina.Sands@matsugov.us>; Amie Jacobs <Amie.Jacobs@matsugov.us>; Katrina Kline <katrina.kline@matsugov.us>; MSB Farmers <MSB.Farmers@matsugov.us>; Permit Center <Permit.Center@matsugov.us>; Code Compliance <Code.Compliance@matsugov.us>; Planning <planning@matsugov.us>; Alex Strawn <Alex.Strawn@matsugov.us>; Fred Wagner <Frederic.Wagner@matsugov.us>; Taunnie Boothby <Taunnie.Boothby@matsugov.us>; msbaddressing <msbaddressing@matsugov.us>; eric.r.schuler@usps.gov; John Aschenbrenner <John.Aschenbrenner@matsugov.us>; Ron Bernier <Ron.Bernier@matsugov.us>; mearow@mea.coop; row@mtasolutions.com; andrew.fraiser@enstarnaturalgas.com; row@enstarnaturalgas.com; ospdesign@gci.com Subject: Meadow Lakes Town Center RSB B/3 L/7

Hello,

Attached is the RFC packet for Meadow Lakes Town Center RSB B/3 L/7. Please ensure that all comments are submitted by February 7, 2025 so that they can be incorporated in the staff report packet that will be presented to the Platting Officer.

Meadow Lks Twn Ctr RSB B3 L7

If you have any questions, feel free to contact me.

Respectfully,

Wyatt Anderson Platting Technician Matanuska Susitna Borough 907-861-7872

Wyatt Anderson

From:

Permit Center

Sent:

Tuesday, January 21, 2025 2:21 PM

To:

Wyatt Anderson

Subject:

RE: Meadow Lakes Town Center RSB B/3 L/7

No comments from permitting.

Thank you,

Jennifer Monnin, CFM
Permit Technician
350 E Dahlia Ave
Palmer, AK 99645
Jennifer.monnin@matsugov.us
907-861-7822



From: Wyatt Anderson < Wyatt. Anderson@matsugov.us>

Sent: Tuesday, January 21, 2025 1:08 PM

Subject: Meadow Lakes Town Center RSB B/3 L/7

To: kristina.huling@alaska.gov; erica.kostelecky@alaska.gov; david.post@alaska.gov; colton.percy@alaska.gov; sarah.myers@alaska.gov; tim.swezey@mlccak.org; psfisherak49@gmail.com; information@mlccak.org; camden.yehle@mlccak.org; mschoming@crweng.com; Tawnya Hightower <Tawnya.Hightower@matsugov.us>; Brian Davis <Brian.Davis@matsugov.us>; Land Management <Land.Management@matsugov.us>; Jillian Morrissey <Jillian.Morrissey@matsugov.us>; Tom Adams <Tom.Adams@matsugov.us>; Brad Sworts <Brad.Sworts@matsugov.us>; Jamie Taylor@matsugov.us>; Daniel Dahms <Daniel.Dahms@matsugov.us>; Tammy Simmons <Tammy.Simmons@matsugov.us>; Christina Sands <Christina.Sands@matsugov.us>; Amie Jacobs <Amie.Jacobs@matsugov.us>; Katrina Kline <katrina.kline@matsugov.us>; MSB Farmers <MSB.Farmers@matsugov.us>; Permit Center <Permit.Center@matsugov.us>; Code Compliance <Code.Compliance@matsugov.us>; Planning <planning@matsugov.us>; Alex Strawn <Alex.Strawn@matsugov.us>; Fred Wagner <Frederic.Wagner@matsugov.us>; Taunnie Boothby <Taunnie.Boothby@matsugov.us>; msbaddressing <msbaddressing@matsugov.us>; eric.r.schuler@usps.gov; John Aschenbrenner <John.Aschenbrenner@matsugov.us>; Ron Bernier <Ron.Bernier@matsugov.us>; mearow@mea.coop; row@mtasolutions.com; andrew.fraiser@enstarnaturalgas.com; row@enstarnaturalgas.com; ospdesign@gci.com

1



Department of Transportation and Public Facilities

4111 Aviation Avenue P.O. Box 196900 Anchorage, AK 99519-6900 Main: 907-269-0520 Fax: 907-269-0521 dot.alaska.gov

January 27, 2025

Fred Wagner, Platting Officer Matanuska-Susitna Borough 350 East Dahlia Avenue Palmer, AK 99645

[Sent Electronically]

Re: Plat Review

Dear Mr. Wagner:

The Alaska Department of Transportation and Public Facilities (DOT&PF) Central Region has reviewed the following plats and have no comments:

Meadow Lks Twn Ctr RSB B3 L7; Plat #2010-73 (Sylvan Road)

The Alaska Department of Transportation and Public Facilities (DOT&PF) Central Region has reviewed the following plats and have the following comments:

- PA 14 HLS Johansson; Tax Parcel D12, Gov't Lots 15 & 17 (Old Glenn Highway)
 - No objection to lot division.
 - o Lot 1 & 2 to share one common access from the Old Glenn Highway.
 - o If access is through Old Glenn Highway, applicant must apply for an Approach Road Review. Approach Road Review's can be applied for at DOT&PF's online ePermits website: https://dot.alaska.gov/row/Login.po. Please contact DOT&PF's ROW division at 1-800-770-5263 to speak with a regional permit officer if you have any questions.
 - Utility connections must be through driveway or approach road and not through the Old Glenn Highway.
 - o https://dot.alaska.gov/permits/
- Dakota Ridge; PA 06 Harmon; Plat #2021-99 (Huntley Road)
 - o No objection to the proposed plat.
 - Platting actions invalidate existing driveway permits. Reapply or apply for new driveway permits at DOT&PF's online ePermits website: https://dot.alaska.gov/row/Login.po.
 Please contact DOT&PF's ROW division at 1-800-770-5263 to speak with a regional permit officer if you have any questions.

- WA 08 North Village; WM Construction; Tax Parcel B19 (MSB owned portion of Bogard Road)
 - This subdivision is within the boundary of the Mat-Su Borough Bogard Road Corridor Access Management Plan (CAMP) which recommends reduced and limited access to Bogard Road throughout the corridor.
 - Mat-Su Borough's Official Streets and Highways Plan at this location shows a frontage road along Bogard Road between Manna Dr and Eminent Domain Circle, and Scott Road development west along the northern section line easement adjacent to this lot.
 - o DOT&PF recommends coordination with the Mat-Su Borough to reconcile subdivision development with road development and interconnectivity plans.
 - o Recommend No Direct Access for all lots to Bogard Road.

All properties accessing DOT&PF roads must apply to Right of Way for a driveway permit and/or approach road review, subject to provisions listed in 17 AAC 10.020. Any previously issued access permits become invalid once the property undergoes a platting action and must be reissued.

We recommend the petitioner verify all section line easements and DOT&PF road rights-of-way adjacent to their property. For assistance, the petitioner may contact the Engineering group within the Right of Way section in DOT&PF at (907) 269-0700. The petitioner is liable to remove any improvements within the easements and rights-of-way that impede the operation and maintenance of those facilities even if they are not shown on the plat, so it is in the petitioner's best interest to identify the exact locations and widths of any such easements or rights-of-way before they improve the property.

If any section line easements or road rights-of-way exist within the bounds of their plat, we recommend the petitioner dedicate them. If there is an existing right-of-way or easement, the petitioner is unable to develop that portion of the property yet continues to pay property taxes on it; dedicating will remove that cost to the petitioner.

If there are any questions regarding these comments, please feel free to contact me at (907) 269-0516 or erica.kostelecky@alaska.gov.

Sincerely,

Erica Kostelecky

Crica Kostelecky

Yukon-Kuskokwim Area Planner, DOT&PF

cc: Sean Baski, Highway Design Chief, DOT&PF

Matt Walsh, Property Management Supervisor, Right of Way, DOT&PF

Devki Rearden, Engineering Associate, DOT&PF

Morris Beckwith, Right of Way, DOT&PF

Brad Sworts, Pre-Design & Engineering Div. Manager, MSB

Anna Bosin, Traffic & Safety Engineer, DOT&PF

Kristina Huling, Mat-Su Area Planner, DOT&PF



ENSTAR Natural Gas Company, LLC

Engineering Department, Right of Way Section 401 E. International Airport Road P. O. Box 190288 Anchorage, Alaska 99519-0288 (907) 277-5551 FAX (907) 334-7798

January 21, 2025

Matanuska-Susitna Borough, Platting Division 350 East Dahlia Avenue Palmer, AK 99645-6488

To whom it may concern:

ENSTAR Natural Gas Company, LLC has reviewed the following preliminary plat and has no comments or recommendations.

• MEADOW LAKES TOWN CENTER LOTS 7A and 7B (MSB Case # 2025-011)

If you have any questions, please feel free to contact me at 334-7944 or by email at james.christopher@enstarnaturalgas.com.

Sincerely,

James Christopher

Right of Way & Compliance Agent ENSTAR Natural Gas Company, LLC

James Christopher

Wyatt Anderson

From:

Cayla Ronken <cronken@mtasolutions.com>

Sent:

Tuesday, January 28, 2025 1:54 PM

To:

Wyatt Anderson

Subject:

RE: Meadow Lakes Town Center RSB B/3 L/7

[EXTERNAL EMAIL - CAUTION: Do not open unexpected attachments or links.]

HI Wyatt,

MTA has existing facilities placed jointly with MEA on lot 7 of plat 2010-73. We will be reaching out to the land owner for a our own easement.

Thank you,

Cayla Ronken, Right of Way Agent

1740 S. Chugach St., Palmer, Alaska 99645

Office: (907) 761-2465 | www.mtasolutions.com




Life. Technology. Together.


From: Wyatt Anderson < Wyatt. Anderson@matsugov.us>

Sent: Tuesday, January 21, 2025 1:08 PM

To: kristina.huling@alaska.gov; erica.kostelecky@alaska.gov; david.post@alaska.gov; colton.percy@alaska.gov; sarah.myers@alaska.gov; tim.swezey@mlccak.org; psfisherak49@gmail.com; information@mlccak.org; camden.yehle@mlccak.org; mschoming@crweng.com; Tawnya Hightower <Tawnya.Hightower@matsugov.us>; Brian Davis <Brian.Davis@matsugov.us>; Land Management <Land.Management@matsugov.us>; Jillian Morrissey <Jillian.Morrissey@matsugov.us>; Tom Adams <Tom.Adams@matsugov.us>; Brad Sworts <Brad.Sworts@matsugov.us>; Jamie Taylor <Jamie.Taylor@matsugov.us>; Daniel Dahms <Daniel.Dahms@matsugov.us>; Tammy Simmons <Tammy.Simmons@matsugov.us>; Christina Sands <Christina.Sands@matsugov.us>; Amie Jacobs <Amie.Jacobs@matsugov.us>; Katrina Kline <katrina.kline@matsugov.us>; MSB Farmers <MSB.Farmers@matsugov.us>; Permit Center <Permit.Center@matsugov.us>; Code Compliance <Code.Compliance@matsugov.us>; Planning <planning@matsugov.us>; Alex Strawn <Alex.Strawn@matsugov.us>; Fred Wagner <Frederic.Wagner@matsugov.us>; Taunnie Boothby <Taunnie.Boothby@matsugov.us>; msbaddressing <msbaddressing@matsugov.us>; eric.r.schuler@usps.gov; John Aschenbrenner <John.Aschenbrenner@matsugov.us>; Ron Bernier <Ron.Bernier@matsugov.us>; mearow@mea.coop; Right of Way Dept. <row@mtasolutions.com>; andrew.fraiser@enstarnaturalgas.com; row@enstarnaturalgas.com; ospdesign@gci.com Subject: Meadow Lakes Town Center RSB B/3 L/7

Hello,





STAFF REVIEW AND RECOMMENDATIONS PUBLIC HEARING FEBRUARY 19, 2025

ABBREVIATED PLAT: DAKOTA RIDGE

LEGAL DESCRIPTION: SEC 25, T18N, R02E S.M., AK

PETITIONERS: JOHN HARMON

SURVEYOR/ENGINEER: LAVENDER/PIONEER ENGINEERING, LLC

ACRES: 10.76 +/- PARCELS: 4

REVIEWED BY: CHRIS CURLIN CASE #: 2025-13

REOUEST:

The request is to create four lots from Lot 1, Brendon Woods (Plat # 2021-99), to be known as Dakota Ridge, containing 10.76 acres +/. The property is located directly north of E. Huntley Road and east of N. Koppenburg Road; within Section 25, Township 18 North, Range 02 East, Seward Meridian, Alaska. In the Lazy Mountain Community Council and Assembly District 1.

EXHIBITS:

Vicinity Map and Aerial Photos

Soils Report

Exhibit A – 4 pgs

Exhibit B –10 pgs

COMMENTS:

ADOT&PF

MSB Pre-Design & Engineering

Utilities

Exhibit C - 2 pgs

Exhibit D - 1 pg

Exhibit E - 2 pgs

<u>DISCUSSION:</u> The proposed subdivision is creating four lots ranging in size from 2 to 3.38 acres. All proposed lots will take access from E. Huntley Road, a DOT&PF owned and maintained road.

<u>Soils Report</u>: A geotechnical report was submitted (Exhibit B), pursuant to MSB 43.20.281(A).Bill Klebesadel, P.E., Working on behalf of the owners and in coordination with Lavender Surveying, we performed a soils investigation for the above-referenced proposed subdivision. The project plans to subdivide the parent parcel into four lots.

Four test holes were excavated on 9-25-24. Each test hole was sited on a proposed lot. All test holes were similar in composition in that they had 1' of topsoil (OL) overlaying silty sand (SM) that extended to the bottom of each test hole at 14 feet. Groundwater was noted at various depths ranging from 8' to 10' deep in test holes 1-3 and 5' deep in test hole #4. No percolation tests were performed,

but samples were taken in each test hole and gradations were performed on those samples. Copies of the soil logs, gradations, and a location map are attached.

The proposed lots have very few limitations on areas defined by MSB code as useable septic area or useable building area. Useable septic areas may be slightly limited by lot lines, topography, and groundwater.

Based on the available soils & water table information, topography, MSB Title 43 Code definitions, and my observations at the site, after regrading Lot 4, each lot will have at least 10,000 square feet of usable building area and at least 10,000 square feet of contiguous usable septic area as required by MSB 43.20.281 AREA.

COMMENTS:

ADOT&PF (Exhibit C) No objection to the proposed plat.

Platting actions invalidate existing driveway permits. Reapply or apply for new driveway permits at DOT&PF's online ePermits website: https://dot.alaska.gov/row/Login.po. Please contact DOT&PF's ROW division at 1-800-770-5263 to speak with a regional permit officer if you have any questions.

MSB Pre-Design & Engineering (Exhibit D) The petitioner should coordinate with AKDOT for access onto Huntley Road. If more than 10,000 sf of grading is required to provide the useable septic area on lot 4, they will need to provide a drainage report showing how the proposed development meets the requirements of SCM section D. Approval of the drainage report from PD&E must take place prior to any regrading work.

Staff notes this is COA # 3.

<u>Utilities:</u> (Exhibit E) ENSTAR has no comments or recommendations. MTA, GCI, & MEA did not respond.

There were no objections received from Borough departments, outside agencies or the public at the time of this staff report.

CONCLUSION

The plat of Dakota Ridge is consistent with AS 29.40.070 *Platting Regulations* and MSB 43.15.025 *Abbreviated Plats*. A soils report was submitted, legal and physical access exist, as-built survey, and topographic information were submitted. There were no objections received from borough departments, outside agencies, utilities, or the public at the time of this staff report.


FINDINGS of FACT:

- 1. The abbreviated plat of Dakota Ridge is consistent with AS 29.40.070 *Platting Regulations*, and MSB 43.15.025 *Abbreviated Plats*.
- 2. A soils report was submitted pursuant to MSB 43.20.281(A). All lots have the required usable area.
- 3. All lots will have the required frontage pursuant to MSB 43.20.320.
- 4. There were no objections from any borough departments, outside agencies, utilities, or the public.
- 5. At the time of staff report write-up, there were no responses to the Request for Comments from Community Council #15 Lazy Mountain; Road Service Area #19 Lazy Mountain; MSB Emergency Services, Community Development, or Assessments; MTA, GCI, or MEA.

RECOMMENDED CONDITIONS OF APPROVAL:


Staff recommends approval of the abbreviated plat of Dakota Ridge, within the SW ¼ Section 25, Township 18 North, Range 02 East, Seward Meridian, Alaska. contingent on the following recommendations:


- 1. Taxes and special assessments must be paid in full for the year of recording, pursuant to MSB 43.15.053(F) and AS 40.15.020. Pay taxes and special assessments (LIDs), by CERTIFIED FUNDS OR CASH.
- 2. Provide updated Certificate to Plat executed within seven (7) days of recording of plat and submit Beneficiary Affidavit for any holders of a beneficial interest.
- 3. Submit a drainage plan pursuant to SCM 2022 and obtain PD&E approval before regrading.
- 4. Provide platting staff an updated soils report after regrading.
- 5. Pay postage and advertising fees.
- 6. Show all easements of record on final plat.
- 7. Submit recording fees, payable to Department of Natural Resources (DNR).
- 8. Submit final plat in full compliance with Title 43.





3 EXHIBIT A-Z 155









Pioneer Engineering LLC Professional, Reliable, Local

December 21, 2024

RE: Usable Area Report

Subdivision of Brendon Woods, Lot 1

Fred Wagner, PLS Platting Officer, Mat-Su Borough 350 E. Dahlia Ave. Palmer, AK 99645

Dear Mr. Wagner,



<u>Description:</u> Working on behalf of the owners and in coordination with Lavender Surveying, we performed a soils investigation for the above-referenced proposed subdivision. The project plans to subdivide the parent parcel into 4 lots (2.06, 2.02, 3.32 and 3.35 acres).

Test Hole:

Four test holes were excavated on 9-25-24. Each test hole was sited on a proposed lot. All test holes were similar in composition in that they had 1' of topsoil (OL) overlaying silty sand (SM) that extended to the bottom of each test hole at 14 feet. Groundwater was noted at various depths ranging from 8' to 10' deep in test holes 1-3 and 5' deep in test hole #4. No percolation tests were performed, but samples were taken in each test hole and gradations were performed on those samples. Copies of the soil logs, gradations, and a location map are attached.

<u>Useable Area:</u> The proposed lots have very few limitations on areas defined by MSB code as *useable septic area* or *useable building area*. Useable septic areas may be slightly limited by lot lines, topography, and groundwater.

Based on the available soils & water table information, topography, MSB Title 43 Code definitions, and my observations at the site, after regrading Lot 4, each lot will have at least 10,000 square feet of usable building area and at least 10,000 square feet of contiguous usable septic area as required by MSB 43.20.281 AREA.

If you have any questions, please do not hesitate to contact me. Thank you for your time.

Sincerely,

Bill Klebesadel, P.E. Owner/Principal Engineer, Pioneer Engineering LLC 16547 E Smith Road Palmer, AK 99645 907-863-2455



Job Number:

2024-SW-305

Project Location: Brendon Woods, Lot 1 - 17001 E Huntley Road

Logged By:

Jacquelyn Kack

9-25-24 Date:

TEST HOLE NO. 1

TEST HOLE NO. 1			
Depth			
(feet)	Description		
0			
1	Topsoil (OL)		
2			
3			
4			
5	Silty sand (SM)		
6			
7			
- 8			
9	Groundwater@9'		
10			
11			
12	Silty sand (SM)		
13			
14			
15	Bottom of test hole		
16			
17	·		
18			
19			
20			
21			



TEST HOLE LOCATION:

See test hole map

COMMENTS:

Soils can support a conventional onsite wastewater system.

Job Number:

2024-SW-305

Project Location: Brendon Woods, Lot 1 - 17001 E Huntley Road

Logged By:

Jacquelyn Kack

9-25-24 Date:

TEST HOLE NO. 3

	TEST HOLE NO. 3
Depth	2.1.2
(feet)	Description
0	
1	Topsoil (OL)
2	
3	
4	
5	Silty sand (SM)
6	only sand (Siri)
7	
8	
9	
10	Groundwater@10'
11	
12	Silty sand (SM)
13	
14	
15	Bottom of test hole
16	
17	
18	
19	
20	
21	



TEST HOLE LOCATION:

See test hole map

COMMENTS:

Soils can support a conventional onsite wastewater system.

Job Number:

2024-SW-305

Project Location: Brendon Woods, Lot 1 - 17001 E Huntley Road

Logged By:

Jacquelyn Kack

Date:

9-25-24

TECT HOLE NO. 4

TEST HOLE NO. 4			
Depth			
(feet)	Description		
0			
1	Topsoil (OL)		
2			
3	Silty sand (SM)		
4			
5	Groundwater@_5'		
6			
7			
- 8			
9			
10	Silty sand (SM)		
11			
12			
13	,		
14			
15	Bottom of test hole		
16			
17			
18			
19			
20			
21			



TEST HOLE LOCATION:

See test hole map

COMMENTS:

Soils can support a conventional onsite wastewater system. Insulation and mounding may be necessary.

Job Number:

2024-SW-305

Project Location: Brendon Woods, Lot 1 - 17001 E Huntley Road

Logged By:

Jacquelyn Kack

Date:

9-25-24

TEST HOLE NO. 2

Depth	
(feet)	Description
0	
1	Topsoil (OL)
2	
3	
4	
5	Silty sand (SM)
6	
_ 7	
8	Groundwater @_8'
9	
10	
11	Silty sand (SM)
12	(4.14)
13	
14	D. C. C. C.
15	Bottom of test hole
16	
17	
18	
19	
20	
21	



TEST HOLE LOCATION:

See test hole map

COMMENTS:


Soils can support a conventional onsite wastewater system.



HANSEN ENGINEERING, INC.

CONSULTING ENGINEERS TESTING LABORATORY Phone: (907) 745-4721 2605 N. Old Glenn Hwy, Palmer, AK 99845

e-mail: mhpe@mtaoniine.net



Client

Pioneer Engineering

Project

Brendon Woods Lot 1

Sample Location: TH #1

Soil Description: Silty Sand with Gravel

Unified Classification: SM

Sample appears to be nonplastic to very low PI

Date

10/30/2024


Sample Date: 9/25/2024

Proj. no:



HANSEN ENGINEERING, INC. CONSULTING ENGINEERS TESTING LABORATORY 2605 N. Old Glenn Hwy, Palmer, AK 99845 Phone: (907) 745-4721

e-mail: mhpe@mtconline.net



Client:

Pioneer Engineering

Project

Brendon Woods Lot 1

Sample Location: TH #2

Unified Classification: SM

Sample appears to be nonplastic to very low PI

Date

10/30/2024


Sample Date: 9/25/2024

Proj. no:



HANSEN ENGINEERING, INC. CONSULTING ENGINEERS TESTING LABORATORY 2605 N. Old Glenn Hwy, Peimer, AK 98845 Phone: (807) 745-4721

e-mall: mhpe@mtconline.net



Client:

Pioneer Engineering

Project Brendon Woods Lot 1

Sample Location: TH #3

Soil Description: Silty Sand with Gravel

Unified Classification: SM

Sample appears to be nonplastic to very low PI

Date

10/30/2024


Sample Date: 9/25/2024

Proj. no:



HANSEN ENGINEERING, INC. CONSULTING ENGINEERS TESTING LABORATORY 2605 N. Old Glenn Hwy, Palmer, AK 98845 Phone: (907) 745-4721

e-mail: mhac@mtconline.net



Client: **Project** **Pioneer Engineering**

Brendon Woods Lot 1

Sample Location: TH #4

Soil Description: Silty Sand with Gravel

Unified Classification: SM


Sample appears to be nonplastic to very low PI

Date

10/30/2024

Sample Date: 9/25/2024

Proj. no:





Department of Transportation and Public Facilities

4111 Aviation Avenue P.O. Box 196900 Anchorage, AK 99519-6900 Main: 907-269-0520 Fax: 907-269-0521 dot.alaska.gov

January 27, 2025

Fred Wagner, Platting Officer Matanuska-Susitna Borough 350 East Dahlia Avenue Palmer, AK 99645

[Sent Electronically]

Re: Plat Review

Dear Mr. Wagner:

The Alaska Department of Transportation and Public Facilities (DOT&PF) Central Region has reviewed the following plats and have no comments:

Meadow Lks Twn Ctr RSB B3 L7; Plat #2010-73 (Sylvan Road)

The Alaska Department of Transportation and Public Facilities (DOT&PF) Central Region has reviewed the following plats and have the following comments:

- PA 14 HLS Johansson; Tax Parcel D12, Gov't Lots 15 & 17 (Old Glenn Highway)
 - No objection to lot division.
 - o Lot 1 & 2 to share one common access from the Old Glenn Highway.
 - o If access is through Old Glenn Highway, applicant must apply for an Approach Road Review. Approach Road Review's can be applied for at DOT&PF's online ePermits website: https://dot.alaska.gov/row/Login.po. Please contact DOT&PF's ROW division at 1-800-770-5263 to speak with a regional permit officer if you have any questions.
 - Utility connections must be through driveway or approach road and not through the Old Glenn Highway.
 - o https://dot.alaska.gov/permits/
- Dakota Ridge; PA 06 Harmon; Plat #2021-99 (Huntley Road)
 - No objection to the proposed plat.
 - Platting actions invalidate existing driveway permits. Reapply or apply for new driveway permits at DOT&PF's online ePermits website: https://dot.alaska.gov/row/Login.po.
 Please contact DOT&PF's ROW division at 1-800-770-5263 to speak with a regional permit officer if you have any questions.

WA 08 North Village; WM Construction; Tax Parcel B19 (MSB owned portion of Bogard Road)

- This subdivision is within the boundary of the Mat-Su Borough Bogard Road Corridor Access Management Plan (CAMP) which recommends reduced and limited access to Bogard Road throughout the corridor.
- Mat-Su Borough's Official Streets and Highways Plan at this location shows a frontage road along Bogard Road between Manna Dr and Eminent Domain Circle, and Scott Road development west along the northern section line easement adjacent to this lot.
- o DOT&PF recommends coordination with the Mat-Su Borough to reconcile subdivision development with road development and interconnectivity plans.
- o Recommend No Direct Access for all lots to Bogard Road.

All properties accessing DOT&PF roads must apply to Right of Way for a driveway permit and/or approach road review, subject to provisions listed in 17 AAC 10.020. Any previously issued access permits become invalid once the property undergoes a platting action and must be reissued.

We recommend the petitioner verify all section line easements and DOT&PF road rights-of-way adjacent to their property. For assistance, the petitioner may contact the Engineering group within the Right of Way section in DOT&PF at (907) 269-0700. The petitioner is liable to remove any improvements within the easements and rights-of-way that impede the operation and maintenance of those facilities even if they are not shown on the plat, so it is in the petitioner's best interest to identify the exact locations and widths of any such easements or rights-of-way before they improve the property.

If any section line easements or road rights-of-way exist within the bounds of their plat, we recommend the petitioner dedicate them. If there is an existing right-of-way or easement, the petitioner is unable to develop that portion of the property yet continues to pay property taxes on it; dedicating will remove that cost to the petitioner.

If there are any questions regarding these comments, please feel free to contact me at (907) 269-0516 or erica.kostelecky@alaska.gov.

Sincerely,

Erica Kostelecky

Erica Kostelecky

Yukon-Kuskokwim Area Planner, DOT&PF

cc: Sean Baski, Highway Design Chief, DOT&PF
Matt Walsh, Property Management Supervisor, Right of Way, DOT&PF
Devki Rearden, Engineering Associate, DOT&PF
Morris Beckwith, Right of Way, DOT&PF
Brad Sworts, Pre-Design & Engineering Div. Manager, MSB
Anna Bosin, Traffic & Safety Engineer, DOT&PF
Kristina Huling, Mat-Su Area Planner, DOT&PF

Chris Curlin

From:

Chris Curlin < Chris. Curlin@matsugov.us>

Sent:

Tuesday, January 28, 2025 4:35 PM

To:

Daniel Dahms

Subject:

RE: Pre-application PA 06 Rumfelt Harmon

Is this for Dakota Ridge?

From: Pre-Design & Engineering <pde@matsugov.us>

Sent: Tuesday, January 28, 2025 4:28 PM **To:** Chris Curlin < Jesse. Curlin@matsugov.us>

Cc: Brad Sworts <Brad.Sworts@matsugov.us>; Jamie Taylor <Jamie.Taylor@matsugov.us>; Tammy Simmons

<Tammy.Simmons@matsugov.us>

Subject: RE: Pre-application PA 06 Rumfelt Harmon

Chris,

The petitioner should coordinate with AKDOT for access onto Huntley Road. If more than 10,000 sf of grading is required to provide the useable septic area on lot 4, the will need to provide a drainage report showing how the proposed development meets the requirements of SCM section D. Approval of the drainage report from PD&E must take place prior to any regrading work.

PD&E

From: Jesse Curlin < Jesse. Curlin@matsugov.us>

Sent: Tuesday, July 16, 2024 2:52 PM

To: Alex Strawn <<u>Alex.Strawn@matsugov.us</u>>; Brad Sworts <<u>Brad.Sworts@matsugov.us</u>>; Brian Davis

- <<u>Brian.Davis@matsugov.us</u>>; Charlyn Spannagel <<u>Charlyn.Spannagel@matsugov.us</u>>; Christina Sands
- <<u>Christina.Sands@matsugov.us</u>>; Code Compliance <Code.Compliance@matsugov.us>; Daniel Dahms
- <Daniel.Dahms@matsugov.us>; Elaine Flagg <Elaine.Flagg@matsugov.us>; Fire Code <Fire.Code@matsugov.us>; Fred

Wagner < Frederic. Wagner@matsugov.us >; Jamie Taylor < Jamie. Taylor@matsugov.us >; John Aschenbrenner

- < John. Aschenbrenner@matsugov.us >; Katrina Kline < katrina.kline@matsugov.us >; Land Management
- <Land.Management@matsugov.us>; Marcia vonEhr < Marcia.vonEhr@matsugov.us>; MSB Farmers
- < MSB.Farmers@matsugov.us>; msbaddressing < msbaddressing@matsugov.us>; Permit Center
- < Permit.Center@matsugov.us >; Planning < MSB.Planning@matsugov.us >; Tammy Simmons
- <<u>Tammy.Simmons@matsugov.us</u>>; Taunnie Boothby <<u>Taunnie.Boothby@matsugov.us</u>>; Tom Adams
- <Tom.Adams@matsugov.us>; David Post <david.post@alaska.gov>; Kristina Huling <kristina.huling@alaska.gov>

Subject: Pre-application PA 06 Rumfelt Harmon

Hello,

The following link is a pre-application request to create four lots from 8169000L001.

Please ensure all comments have been submitted by August 1, 2024 so they can be incorporated in the pre-application notes packet that will be returned to the petitioner.

PA 00 Ruilliell Haillion	□ PA 06	Rumfelt	Harmon
--------------------------	---------	---------	--------



ENSTAR Natural Gas Company, LLC

Engineering Department, Right of Way Section 401 E. International Airport Road P. O. Box 190288 Anchorage, Alaska 99519-0288 (907) 277-5551 FAX (907) 334-7798

January 28, 2025

Matanuska-Susitna Borough, Platting Division 350 East Dahlia Avenue Palmer, AK 99645-6488

To whom it may concern:

ENSTAR Natural Gas Company, LLC has reviewed the following abbreviated plat and has no comments or recommendations.

 DAKOTA RIDGE (MSB Case # 2025-013)


If you have any questions, please feel free to contact me at 334-7944 or by email at james.christopher@enstarnaturalgas.com.


Sincerely,

James Christopher

Right of Way & Compliance Agent ENSTAR Natural Gas Company, LLC

James Christopher





STAFF REVIEW AND RECOMMENDATIONS PUBLIC HEARING FEBRUARY 19, 2025

ABBREVIATED PLAT: SCORPION

LEGAL DESCRIPTION: SEC 07, T17N, R01W, SEWARD MERIDIAN AK

PETITIONERS: DAN HACKER

SURVEYOR/ENGINEER: BUSH CONSTRUCTION SERVICES

ACRES: $4.3 \pm$ PARCELS: 2

REVIEWED BY: MATTHEW GODDARD CASE #: 2025-014

REQUEST: The request is to create two lots from Lot 1A, McCallister Subdivision, Plat No. 2014-11 to be known as **SCORPION**, containing 4.3 acres +/-. The property is located north of the Alaska Railroad, east of N. Stanley Road, and directly south of W. Parks Highway; within the NW ¼ Section 07, Township 17 North, Range 01 West, Seward Meridian, Alaska. In the Meadow Lakes Community Council and in Assembly District #7.

EXHIBITS

Vicinity Map and Aerial Photos	EXHIBIT $A - 5$ pgs
Soils Report	EXHIBIT B -13 pgs
As-Built	EXHIBIT $C - 1 pg$

AGENCY COMMENTS

ADOT&PF	EXHIBIT D -2 pgs
MSB DPW PD&E	EXHIBIT E -1 pg
MSB Planning	EXHIBIT F -2 pgs
MSB Permit Center	EXHIBIT G -1 pg
MSB Fire & Life Safety	EXHIBIT H -1 pg
Utilities	EXHIBIT I -3 pgs

<u>**DISCUSSION**</u>: The proposed subdivision is creating two lots from Lot 1A, McCallister Subdivision, Plat #2014-11. Access is from S. McCallister Drive, a Borough maintained road.

Soils Report: A geotechnical report was submitted (**Exhibit B**), pursuant to MSB 43.20.281(A). Timothy Alley, Registered Professional Engineer, notes the proposed subdivision creates two lots in excess of 40,000 sf. Lot 2 area equal to 3.2 acres and Lot 1 area equal to 1.1 acres. Two test pit soil explorations were observed in November 2017 and June 2018. Test pits were excavated to a depth of 12.5' and 12', no ground water was encountered. There were no slopes onsite greater than 25%. There is an 82' PLO located along the northern property boundary, the usable septic and building area are outside of this PLO. Permafrost was not suspected nor encountered. Receiving soils were found to be poorly graded gravel (GP) and are expected to have a percolation rate greater than 15 minutes per inch. Both lots 1 and 2 will be greater than 40,000 SF. All areas outside of required setbacks per MSB code have been determined to be "Usable Building

Area" and exceeds 10,000 SF per lot. Based on soil tests pit there is an additional contiguous 10,000 SF available for septic area on each lot.

As-Built/Topographic Mapping: An as-built with topographic contour lines was submitted (Exhibit C). Based on the provided as-built information, there are no existing setback violations and no new violations would be created by the proposed subdivision.

Comments:

Alaska Department of Transportation & Public Facilities (**Exhibit D**) has the following comments:

- No objection to the proposed plat.
- No direct access shall be granted to the Parks Highway (**Recommendation #4**).
- DOT&PF recommends the Mat-Su Borough consider through road development gals in the area of Seims Street between the Parks Highway and McCallister Drive.
- DOT&PF requests that the applicant doesn't develop anything that precludes a future connection of Seims Street between the Parks Highway and McCallister Drive.

MSB DPW Pre-Design and Engineering Division (Exhibit E) The petitioner should provide a figure showing how a driveway could be constructed to Lot 1 that meets the current driveway standards or the plat should include shared access for the lots.

Platting staff notes that while not a requirement, should a shared access be needed to provide driveway access, it is recommended that a common access easement be added at the design allowing for shared access.

MSB Planning Department (Exhibit F) notes that a marijuana retail and standard cultivation permit (M10165 & M10166) was issued on this property in 2019. Since then, expansion has occurred on the north, west, and south sides of the commercial building depicted in the survey. MSB 17.60 requires permits to be modified if the operation expands and/or significant changes occur.

- 1. Standard Marijuana Cultivation CUPs require a 100' setback distance from the side and rear lot lines and 50' from rights-of-way, according to MSB 17.60.160. A portion of the building on the north side of the commercial structure is less than 100' from the nearest lot line. The operation is permitted to operate within the footprint described in the application and approved by PC Resolution 19-05. The standard marijuana cultivation operation must maintain the required setback distances according to MSB 17.60.
- 2. Retail marijuana CUP M10165 was issued in 2019 after PC Resolution 19-06 was approved, which did not include a drive-thru/walk-up window. A drive-thru/walk-up window is only authorized upon a modification to the existing CUP.

Platting staff notes that upon discussion with Rick Benedict, this comment is for informational purposes and the existing property is currently in compliance with CUPs M10165 & M10166.

MSB Permit Center (**Exhibit G**) has no comments.

MSB Fire & Life Safety Division (Exhibit H) notes that this proposal may affect a structure regulated by their office for conformity to the Fire and Life Safety Standards as per AS 18.70.080. Before beginning the construction, alteration, repair, or changing the occupancy of a building, substantial land structure, or structure regulated by the state division of fire and life safety, plans and specifications need to be submitted to their office. 13 AAC 50.027.

<u>Utilities</u>: (Exhibit F) ENSTAR advises that there is an existing ten foot wide natural gas easement located within proposed Lot 1. Please show this 10 foot wide natural gas easement as depicted on McCallister Subdivision Lot 1A, 2A, and 3A, Block 1, filed under Plat No. 2014-11, in the records of the Palmer Recording District, Third Judicial District, State of Alaska.

Platting staff notes that all easements of record will be shown on the final mylar (**Recommendation #5**)

At the time of staff report write-up, there were no responses to the Request for Comments from ADF&G; USACE; Community Council #1 Meadow Lakes; Road Service Area #27 Meadow Lakes; MSB Community Development, or Assessments; GCI, MEA, or MTA.


<u>CONCLUSION</u>: The abbreviated plat of Scorpion is consistent with AS 29.40.070 Platting Regulations and MSB 43.15.025 Abbreviated Plats. There were no objections from any federal or state agencies, Borough departments, or utilities. There were no objections to the plat from the public in response to the Notice of Public Hearing. Legal and physical access exists to the proposed lots, consistent with MSB 43.20.100 Access Required, MSB 43.20.120 Legal Access and MSB 43.20.140 Physical Access. Frontage for the subdivision exists, pursuant to MSB 43.20.320 Frontage. A soils report was submitted, pursuant to MSB 43.20.281(A)(1).


FINDINGS OF FACT

- 1. The plat of Scorpion is consistent with AS 29.40.070 Platting Regulations and MSB 43.15.025 Abbreviated Plats.
- 2. A soils report was submitted, pursuant to MSB 43.20.281(A)(1).
- 3. Both lots will have legal and physical access consistent with MSB 43.20.100, MSB 43.20.120 and MSB 43.20.140.
- 4. Both lots have the required frontage pursuant to MSB 43.20.320.
- 5. At the time of staff report write-up, there were no responses to the Request for Comments from ADF&G; USACE; Community Council #1 Meadow Lakes; Road Service Area #27 Meadow Lakes; MSB Community Development, or Assessments; GCI, MEA, or MTA.
- 6. There were no objections from any federal or state agencies, or Borough departments.
- 7. There were no objections from the public in response to the Notice of Public Hearing.


<u>RECOMMENDATIONS OF CONDITIONS OF APPROVAL</u> for the abbreviated plat of Scorpion, Section 07, Township 17 North, Range 01 West, Seward Meridian, Alaska, contingent on staff recommendations:


- 1. Taxes and special assessments must be paid in full for the year of recording, pursuant to MSB 43.15.053(F) and AS 40.15.020. Pay taxes and special assessments (LIDs), by CERTIFIED FUNDS OR CASH.
- 2. Provide updated Certificate to Plat executed within seven (7) days of recording of plat and submit Beneficiary Affidavit for any holders of a beneficial interest.
- 3. Pay postage and advertising fees.
- 4. Add a plat note stating, "No direct access shall be granted to the W. Parks Highway unless otherwise authorized by the permitting authority."
- 5. Show all easements of record on final plat.
- 6. Submit recording fees, payable to Department of Natural Resources (DNR).
- 7. Submit final plat in full compliance with Title 43.





February 12, 2025 Abbreviated Plat Hearing Packet





February 12, 2025 Abbreviated Plat Hearing Packet 60 of 116 Snead Loop N Coghlan Cir W Machen Rd Little Rd **HO**09 W Parks Hwy Jacobsen Lake
Jacobsen Lake W Aviation Ave MatSuBorough

205

410

410 Feet



The Boutet Company, Inc. 1508 E. Bogard Road, Unit 7 Wasilla, Alaska 99654 Phone 907.357.6770 www.tbcak.com

November 18, 2024

Mr. Fred Wagner, LS
Matanuska-Susitna Borough
Platting Department
350 E. Dahlia Avenue
Palmer, Alaska 99645



RE: Usable Area Report

Mccallister RSB T/B & B/1 L/2 Block 1 Lot 1A

Dear Mr. Wagner,

The applicant McCallister Investment Group is proposing to subdivide Mccallister RSB T/B & B/1 L/2 Block 1 Lot 1A into two lots.

The subject property is within the Matanuska-Susitna Borough Core Area and located outside any city limits. The lots created in the proposed subdivision will be/are served by onsite private water and septic systems. Both the water and septic system will be designed and installed per Department of Environmental Conservation Regulations.

Pursuant to MSB Platting Code 43.20, Lots will require usable area as defined by 43.20.281. The following Usable Area Report is intended to address these two tracts. The existing lot currently has a structure and septic system constructed. Below are criteria responses to the applicable portions of the Matanuska-Susitna Borough Code defining area requirements for subdivisions:

43.20.281 AREA

- (A) Unless designated otherwise by another authority having jurisdiction, minimum lot sizes shall be as follows:
- (1) Except as allowed under subsections (A)(2), (3), and (4) of this section, all lots within this district shall contain at least 40,000 square feet of area with at least 10,000 square feet of usable building area and 10,000 square feet of contiguous usable septic area. Lots having 20,000 square feet or less of the total of usable building area and usable septic area shall have 10,000 square feet of contiguous usable septic area surrounded by a well exclusion area extending 100 feet from the perimeter, delineated and reserved on the plat at the discretion of the platting board.

Proposed subdivision creates two lots in excess of 40,000 sf. Lot 2 area equal to 3.2 acres and Lot 1 area equal to 1.1 acres.

November 18, 2024 Mr. Fred Wagner, LS McCallister Subdivision Usable Area Report Page 2 of 4

(a) Usable septic area is that area where seasonal high water table is a minimum of eight feet below the surface. Where water is encountered at ten feet or less below the surface, the seasonal high subsurface water is to be determined between May 1st and October 30th, and:

The civil engineer, Tim Alley, PE, directed and observed two test pit soil explorations in November 2017 and June 2018. The soils logs may be found attached to this document.

- (i) that area where slopes are less than 25 percent; There are no slopes onsite greater than 25%.
- (ii) that area which is more than 100 feet from open water, surface waters, and wetlands;

 The entirety of the lot being subdivide is greater than 100 feet from open water, surface water and wetlands.
- (iii) that area which is located at least 50 feet from the top of a slope which is greater than 25 percent and has more than ten feet of elevation change;

Not applicable to this site.

- (iv) that area which is not within an area dedicated to public use;

 An 82' PLO is located along the northern property boundary. The usable septic and building area are outside of this PLO.
- (v) that area which is outside of utility or other easements that would affect the use of the areas for on-site septic installation;

Acknowledged.

- (vi) that area which is outside of a protective well radius; Acknowledged.
- (vii) that area which is outside of any known debris burial site; and No known burial area on site.
- (viii) [Repealed by Ord. 17-033, § 55, 2017]
- (b) Water table and ability of soils to accept effluent shall be determined by a number of borings or test holes sufficient to indicate subsurface conditions over the entire area of the subdivision. All of the borings and test holes shall be located within the perimeter of the proposed subdivision. Borings and test holes must have the following minimum depths below the ground surface:
- (i) in areas known or suspected to contain permafrost, the lesser of:

 Permafrost was not suspected, nor encountered.

November 18, 2024 Mr. Fred Wagner, LS McCallister Subdivision Usable Area Report Page 3 of 4

- (ii) the least depth associated with the following conditions, where they apply:
- (aa) two feet below the depth where the water table is encountered;

 Test pits were excavated to a depth of 12.5' and 12'. No groundwater was encountered.
- (bb) twelve feet deep for shallow trench or bed systems;
 The engineer is anticipating a bed systems with sand liners be used due to the clean gravel (GP) soils within the absorption areas.
- (cc) sixteen feet deep for areas where deep trench or seepage pits will likely be used; See (bb).
- (dd) the depth to bedrock, clay, or other impermeable strata with an expected percolation rate slower than 120 minutes per inch; or

None of the above criteria were encountered.

- (ee) As determined by the engineer, a lesser depth as required to verify usable areas is acceptable for hand-dug excavations on parcels with limited or no access for heavy equipment.
- (c) The minimum number of test holes shall be determined by the engineer.

 The 2017 test pit was excavated Approximately 30' northwest of the midpoint of the southeastern property line of Lot 1A. A second test pit was excavated on June 18, 2018 approximately 150' east of the western property line and 50' north of the southern property line.
- (d) When the water table is encountered in the test holes, the depth to the seasonal high water table must be determined by:

No groundwater encountered.

- (e) The depth to any seeps must be noted and may require subsequent monitoring.

 No seeps were encountered during the soils investigation.
- (f) Soils in a usable wastewater disposal area must be:
- (i) clearly shown to be visually classified as GW, GP, SW, or SP under the Unified Soils Classification System and expected to have a percolation rate of 15 minutes per inch or less (faster);

Only the top 2' in the test holes contained silty sand and gravel. The soil strata in the location (approximately 4'-5' below ground surface) of an absorption field and below were found to be poorly graded gravel (GP) expected to have a percolation rate greater than 15 minutes per inch.

November 18, 2024 Mr. Fred Wagner, LS McCallister Subdivision Usable Area Report Page 4 of 4

(ii) clearly shown to be GM or SM under the Unified Soils Classification System by a sieve analysis; or

GM soils were not encountered in this test pit.

(iii) shown by a percolation test conducted in accordance with (ADEC) Alaska State
Department of Environmental Conservation regulations to have a percolation rate of 60 minutes
per inch or less (faster).

Due to the visual identification of gravel (GP) soils, a percolation test was not required.

(g) These borings or test holes shall be accomplished under the direct supervision of a state of Alaska registered civil engineer, who shall submit soil logs and other findings in writing to the Matanuska-Susitna Borough certifying 10,000 square feet of contiguous usable area for septic drain field use.

Both lots 1 and 2 will be greater than 40,000 SF. All areas outside of required setbacks per MSB code have been determined to be "Usable Building Area" and exceeds 10,000 SF per lot. Based on soil tests pit there is an additional contiguous 10,000 SF available for septic area on each lot.

If you have any questions, please contact me with any questions you may have.

Sincerely,

Timothy Alley, PE
Principal/Vice President
The Boutet Company, Inc
1508 E. Bogard Rd #7
Wasilla, AK 99654
(907) 357-6760
talley@tbcak.com

Job Number:				
Project Location:	McCallister Lot 1A		***	
Logged By:	Tim Allev	Date:	11-08-2017	

TEST HOLE NO. 2017

TEST HOLE NO. 2017		
Depth		
(feet)	Description	
0		
1	Organics, with silt	
1	Silty Sand with Gravel (SM/GM),	
2	Tan/Brown	
3		
4	Poorly graded Sandy Gravel (GP), Brown	
5		
6		
7		
8	, 1	
9	Sandy Gravels (GP), grey	
10		
11		
12		
12	12' Bottom of test hole (No Groundwater	
13	Encountered)	
14		
15		
16		
17		
18		
19		
20		

TEST HOLE LOCATION:

Approximately 50' northwest of the mid point of the southeastern property line. See attached.

COMMENTS:

Job Number:					
Project Location:	McCallister Lot 1A	:			
	* ,				
Logged By:	Tim Alley		Date:	06-18-2018	


TEST HOLE NO. 2018

TEST HOLE NO. 2018			
Depth			
(feet)	Description		
0			
1	Organics, with silt		
	Silty Sand with Gravel (SM/GM),		
2	Tan/Brown		
3			
	Poorly graded Sandy Gravel (GP), Brown		
4			
5			
6			
7			
/			
8			
9	Sandy Gravels (GP), grey		
10			
11			
12			
13	12.5' Bottom of test hole (No Groundwater		
13	Encountered)		
14			
15			
13			
16			
17			
17			
18			
19			
20			

TEST HOLE LOCATION:

Approximately 50' north of the south property line and 150' east of the west property line

COMMENTS:





The Boutet Company, Inc. 1508 E. Bogard Road, Unit 7 Wasilla, Alaska 99654 Phone 907.357.6770 www.tbcak.com

October 7, 2024

Mr. Fred Wagner, LS Matanuska-Susitna Borough Platting Department 350 E. Dahlia Avenue Palmer, Alaska 99645



RE: Usable Area Report

Mccallister RSB T/B & B/1 L/2 Block 1 Lot 1A

Dear Mr. Wagner,

The applicant McCallister Investment Group is proposing to subdivide Mccallister RSB T/B & B/1 L/2 Block 1 Lot 1A into two lots.

The subject property is within the Matanuska-Susitna Borough Core Area and located outside any city limits. The lots created in the proposed subdivision will be/are served by onsite private water and septic systems. Both the water and septic system will be designed and installed per Department of Environmental Conservation Regulations.

Pursuant to MSB Platting Code 43.20, Lots 1 will require usable area as defined by 43.20.281. The following Usable Area Report is intended to address these two tracts. Lot currently has a structure and septic system constructed. Below are criteria responses to the applicable portions of the Matanuska-Susitna Borough Code defining area requirements for subdivisions:

43.20.281 AREA

- (A) Unless designated otherwise by another authority having jurisdiction, minimum lot sizes shall be as follows:
- (1) Except as allowed under subsections (A)(2), (3), and (4) of this section, all lots within this district shall contain at least 40,000 square feet of area with at least 10,000 square feet of usable building area and 10,000 square feet of contiguous usable septic area. Lots having 20,000 square feet or less of the total of usable building area and usable septic area shall have 10,000 square feet of contiguous usable septic area surrounded by a well exclusion area extending 100 feet from the perimeter, delineated and reserved on the plat at the discretion of the platting board.

Proposed subdivision creates two lots in excess of 40,000 sf. Lot 2 area equal to 3.2 acres and Lot 1 area equal to 1.1 acres.

October 7, 2024 Mr. Fred Wagner, LS McCallister Subdivision Usable Area Report Page 2 of 4

(a) Usable septic area is that area where seasonal high water table is a minimum of eight feet below the surface. Where water is encountered at ten feet or less below the surface, the seasonal high subsurface water is to be determined between May 1st and October 30th, and:

The civil engineer directed and observed test pit soil exploration in November 2017. The soils log may be found attached to this document.

- (i) that area where slopes are less than 25 percent; There are no slopes onsite greater than 25%.
- (ii) that area which is more than 100 feet from open water, surface waters, and wetlands;

 The entirety of the lot being subdivide is greater than 100 feet from open water, surface water and wetlands.
- (iii) that area which is located at least 50 feet from the top of a slope which is greater than 25 percent and has more than ten feet of elevation change;

Not applicable to this site.

- (iv) that area which is not within an area dedicated to public use;

 An 82' PLO ius locate along the northern property boundary. The usable septic and building area are outside of this PLO.
- (v) that area which is outside of utility or other easements that would affect the use of the areas for on-site septic installation;

Acknowledged.

- (vi) that area which is outside of a protective well radius;Acknowledged.
- (vii) that area which is outside of any known debris burial site; and No known burial area on site.
- (viii) [Repealed by Ord. 17-033, § 55, 2017]
- (b) Water table and ability of soils to accept effluent shall be determined by a number of borings or test holes sufficient to indicate subsurface conditions over the entire area of the subdivision. All of the borings and test holes shall be located within the perimeter of the proposed subdivision. Borings and test holes must have the following minimum depths below the ground surface:
- (i) in areas known or suspected to contain permafrost, the lesser of: Permafrost was not suspected, nor encountered.

October 7, 2024 Mr. Fred Wagner, LS McCallister Subdivision Usable Area Report Page 3 of 4

- (ii) the least depth associated with the following conditions, where they apply:
- (aa) two feet below the depth where the water table is encountered;

 Test pit was excavated to a depth of 12'. No groundwater was encountered.
- (bb) twelve feet deep for shallow trench or bed systems;

 The engineer is anticipating a bed system with sand liner be used due to the clean gravel (GP) soils within the absorption area.
- (cc) sixteen feet deep for areas where deep trench or seepage pits will likely be used; See (bb).
- (dd) the depth to bedrock, clay, or other impermeable strata with an expected percolation rate slower than 120 minutes per inch; or

None of the above criteria were encountered.

- (ee) As determined by the engineer, a lesser depth as required to verify usable areas is acceptable for hand-dug excavations on parcels with limited or no access for heavy equipment.
- (c) The minimum number of test holes shall be determined by the engineer.

 The 2017 test pit was excavated Approximately 30' northwest of the midpoint of the southeastern property line of Lot 1A. A septic system has already been installed on Lot 2 and adequate area is available for a replacement system if/when needed.
- (d) When the water table is encountered in the test holes, the depth to the seasonal high water table must be determined by:

No groundwater encountered.

- (e) The depth to any seeps must be noted and may require subsequent monitoring.

 No seeps were encountered during the soils investigation.
- (f) Soils in a usable wastewater disposal area must be:
- (i) clearly shown to be visually classified as GW, GP, SW, or SP under the Unified Soils Classification System and expected to have a percolation rate of 15 minutes per inch or less (faster);

Only the top 2' in the test hole contained silty sand and gravel. The soil strata in the location (approximately 4' below ground surface) of an absorption field and below were found to be poorly graded gravel (GP) expected to have a percolation rate greater than 15 minutes per inch.

October 7, 2024 Mr. Fred Wagner, LS McCallister Subdivision Usable Area Report Page 4 of 4

(ii) clearly shown to be GM or SM under the Unified Soils Classification System by a sieve analysis; or

GM soils were not encountered in this test pit.

(iii) shown by a percolation test conducted in accordance with (ADEC) Alaska State
Department of Environmental Conservation regulations to have a percolation rate of 60 minutes
per inch or less (faster).

Due to the visual identification of gravel (GP) soils, a percolation test was not required.

(g) These borings or test holes shall be accomplished under the direct supervision of a state of Alaska registered civil engineer, who shall submit soil logs and other findings in writing to the Matanuska-Susitna Borough certifying 10,000 square feet of contiguous usable area for septic drain field use.

Both lots 1 and 2 will be greater than 40,000 SF. All areas outside of required setbacks per MSB code have been determined to be "Usable Building Area" and exceeds 10,000 SF per lot. Note, lot 2 currently has a structure and septic system installed. Based on soil test pit there is an additional 10,000 SF available for septic area on Lot 1.

If you have any questions, please contact me with any questions you may have.

Sincerely,


Timothy Alley, PE Principal/Vice President The Boutet Company, Inc 1508 E. Bogard Rd #7 Wasilla, AK 99654 (907) 357-6760 talley@tbcak.com


Job Number:		_		
Project Location:	McCallister Lot 1A		, , , , , , , , , , , , , , , , , , ,	
Logged By:	Tim Alley	Date:	11-08-2017	

	TEST HOLE NO. 1	
Depth (feet)	Description	
	Description	
0	Organics, with silt	
1	Silty Sand with Gravel (SM/GM),	
2	Tan/Brown	1
3		
4	Poorly graded Sandy Gravel (GP), Brown	
5		1, 1
6		
7		
8		TEST HOLE LOCATION:
9	Sandy Gravels (GP), grey	Approximately 50' northwest of t the southeastern property line. Se
10		GOLD FEVE
11		COMMENTS:
12		
13	12' Bottom of test hole (No Groundwater Encountered)	
14		This soil log was prepared for the sole p
15		determining the feasibility of construction onsite wastewater disposal system at the
16		of the test hole. Soil type ratings are ba visual observation and have not been ve
17		with laboratory analyses. These soils habeen analyzed for structural stability or
18		purpose other than wastewater absorption construction. Anyone relying on this in
19		for any use other than wastewater absor field development shall do so at their ov
20		

the mid point of See attached.

purpose of ting an ne location ased on erified nave not for any ion field nformation orption own risk.







Department of Transportation and Public Facilities

4111 Aviation Avenue P.O. Box 196900 Anchorage, AK 99519-6900 Main: 907-269-0520 Fax: 907-269-0521 dot.alaska.gov

January 31, 2025

Fred Wagner, Platting Officer Matanuska-Susitna Borough 350 East Dahlia Avenue Palmer, AK 99645

[Sent Electronically]

Re: Plat Review

Dear Mr. Wagner:

The Alaska Department of Transportation and Public Facilities (DOT&PF) Central Region has reviewed the following plats and have the following comments:

Scorpion, WA 12 Hacker, Plat #2014-11 (Parks Highway)

- No objection to the proposed plat.
- No direct access to the Parks Highway will be granted. All proposed lots must take access from McCallister Dr.
- DOT&PF recommends the Mat-Su Borough consider through road development goals in the area of Seims Street between the Parks Highway, Coghlan Circle and McCallister Dr.
- O DOT&PF requests applicant doesn't develop anything that precludes a future connection of Seims Street between the Parks Highway and McCallister Dr.

HO 16 BMS Molodkin, Plat#72-80 (Knik Goose Bay Rd)

- o No objection to the proposed lot line adjustment.
- o No direct access to Knik Goose Bay Road will be granted.
- o Lots 4 & 10 to take access from Paper Birch Lane.
- o DOT&PF recommends shared access for all subsequent development.

All properties accessing DOT&PF roads must apply to Right of Way for a driveway permit and/or approach road review, subject to provisions listed in 17 AAC 10.020. Any previously issued access permits become invalid once the property undergoes a platting action and must be reissued.

We recommend the petitioner verify all section line easements and DOT&PF road rights-of-way adjacent to their property. For assistance, the petitioner may contact the Engineering group within the Right of Way section in DOT&PF at (907) 269-0700. The petitioner is liable to remove any improvements within the easements and rights-of-way that impede the operation and maintenance of

those facilities even if they are not shown on the plat, so it is in the petitioner's best interest to identify the exact locations and widths of any such easements or rights-of-way before they improve the property.

If any section line easements or road rights-of-way exist within the bounds of their plat, we recommend the petitioner dedicate them. If there is an existing right-of-way or easement, the petitioner is unable to develop that portion of the property yet continues to pay property taxes on it; dedicating will remove that cost to the petitioner.

If there are any questions regarding these comments, please feel free to contact me at (907) 269-0516 or erica.kostelecky@alaska.gov.

Sincerely,

Erica Kostelecky

Crica Kostelecky

Yukon-Kuskokwim Area Planner, DOT&PF

cc: Sean Baski, Highway Design Chief, DOT&PF

Matt Walsh, Property Management Supervisor, Right of Way, DOT&PF

Devki Rearden, Engineering Associate, DOT&PF

Morris Beckwith, Right of Way, DOT&PF

Brad Sworts, Pre-Design & Engineering Div. Manager, MSB

Anna Bosin, Traffic & Safety Engineer, DOT&PF Kristina Huling, Mat-Su Area Planner, DOT&PF

From:

Pre-Design & Engineering

Sent:

Tuesday, January 28, 2025 3:47 PM

To:

Matthew Goddard

Cc:

Brad Sworts; Jamie Taylor; Tammy Simmons

Subject:

RE: RFC Scorpion (MG)

Matthew,

The petitioner should provide a figure showing how a driveway could be constructed to Lot 1 that meets the current driveway standards or the plat should include shared access for the lots.

PD&E

From: Matthew Goddard < Matthew. Goddard@matsugov.us>

Sent: Wednesday, January 22, 2025 3:43 PM

To: Huling, Kristina N (DOT) <kristina.huling@alaska.gov>; Post, David E (DOT) <david.post@alaska.gov>; Kostelecky, Erica D (DOT) <erica.kostelecky@alaska.gov>; Myers, Sarah E E (DFG) <sarah.myers@alaska.gov>; Percy, Colton T (DFG) <colton.percy@alaska.gov>; regpagemaster@usace.army.mil; Tim Swezey <tim.swezey@mlccak.org>; psfisherak49@gmail.com; information@mlccak.org; Camden Yehle <camdenyehle@gmail.com>; lana@mtaonline.net; Michael Keenan <Michael.Keenan@matsugov.us>; Jeffrey Anderson <Jeffrey.Anderson@matsugov.us>; Fire Code <Fire.Code@matsugov.us>; Brian Davis <Bri>Brian.Davis@matsugov.us>; Ron Bernier <Ron.Bernier@matsugov.us>; Land Management <Land.Management@matsugov.us>; Jillian Morrissey <Jillian.Morrissey@matsugov.us>; Tom Adams <Tom.Adams@matsugov.us>; Brad Sworts <Brad.Sworts@matsugov.us>; Jamie Taylor <Jamie.Taylor@matsugov.us>; Daniel Dahms <Daniel.Dahms@matsugov.us>; Tammy Simmons <Tammy.Simmons@matsugov.us>; Christina Sands <Christina.Sands@matsugov.us>; Amie Jacobs <Amie.Jacobs@matsugov.us>; Katrina Kline

- <katrina.kline@matsugov.us>; MSB Farmers <MSB.Farmers@matsugov.us>; Permit Center
- <Permit.Center@matsugov.us>; Code Compliance <Code.Compliance@matsugov.us>; Planning
- <MSB.Planning@matsugov.us>; Alex Strawn <Alex.Strawn@matsugov.us>; Fred Wagner
- <Frederic.Wagner@matsugov.us>; Taunnie Boothby <Taunnie.Boothby@matsugov.us>; msbaddressing
- <msbaddressing@matsugov.us>; eric.r.schuler@usps.gov; John Aschenbrenner <John.Aschenbrenner@matsugov.us>; Andrew Fraiser <andrew.fraiser@enstarnaturalgas.com>; ROW <row@enstarnaturalgas.com>; Right of Way Dept.
- <row@mtasolutions.com>; OSP Design Group <ospdesign@gci.com>; mearow@mea.coop; Peggy Horton
- <Peggy.Horton@matsugov.us>; Rick Benedict <Rick.Benedict@matsugov.us>; Natasha Heindel
- <Natasha.Heindel@matsugov.us>

Subject: RFC Scorpion (MG)

Hello,

The following link is a request for comments for the proposed Scorpion Subdivision.

Please ensure all comments have been submitted by February 3, 2025, so they can be incorporated into the staff report that will be presented to the Platting Officer.

Sco	rn	ion
SCU		IOH

Feel free to contact me if you have any questions.

Thank you,

From:

Rick Benedict

Sent:

Monday, January 27, 2025 11:04 AM

To:

Matthew Goddard

Subject:

RE: RFC Scorpion (MG)

A marijuana retail and standard cultivation permit (M10165 & M10166) was issued on this property in 2019. Since then, expansion has occurred on the north, west, and south sides of the commercial building depicted in the survey. MSB 17.60 requires permits to be modified if the operation expands and/or significant changes occur.

- 1) Standard marijuana cultivation CUPs require a 100' setback distance from the side and rear lot lines and 50' from rights-of-way, according to MSB 17.60.160. A portion of the building on the north side of the commercial structure is less than 100' from the nearest lot line. The operation is permitted to operate within the footprint described in the application and approved by PC Resolution 19-05. The standard marijuana cultivation operation must maintain the required setback distances according to MSB 17.60.
- 2) Retail marijuana CUP M10165 was issued in 2019 after PC Resolution 19-06 was approved, which did not include a drive-thru/walk-up window. A drive-thru/walk-up window is only authorized upon a modification to the existing CUP.

For questions or clarification on the requirements of MSB 17.60 or issued permits, please contact a member of the Current Planner staff.

MSB Planning Department Development Services Division Current Planners (907) 861-7822

From: Matthew Goddard < Matthew. Goddard@matsugov.us>

Sent: Wednesday, January 22, 2025 3:43 PM

To: Huling, Kristina N (DOT) < kristina.huling@alaska.gov>; Post, David E (DOT) < david.post@alaska.gov>; Kostelecky, Erica D (DOT) <erica.kostelecky@alaska.gov>; Myers, Sarah E E (DFG) <sarah.myers@alaska.gov>; Percy, Colton T (DFG) <colton.percy@alaska.gov>; regpagemaster@usace.army.mil; Tim Swezey <tim.swezey@mlccak.org>; psfisherak49@gmail.com; information@mlccak.org; Camden Yehle <camdenyehle@gmail.com>; lana@mtaonline.net; Michael Keenan < Michael. Keenan@matsugov.us>; Jeffrey Anderson < Jeffrey. Anderson@matsugov.us>; Fire Code <Fire.Code@matsugov.us>; Brian Davis <Brian.Davis@matsugov.us>; Ron Bernier <Ron.Bernier@matsugov.us>; Land Management <Land.Management@matsugov.us>; Jillian Morrissey <Jillian.Morrissey@matsugov.us>; Tom Adams <Tom.Adams@matsugov.us>; Brad Sworts <Brad.Sworts@matsugov.us>; Jamie Taylor <Jamie.Taylor@matsugov.us>; Daniel Dahms <Daniel.Dahms@matsugov.us>; Tammy Simmons <Tammy.Simmons@matsugov.us>; Christina Sands <Christina.Sands@matsugov.us>; Amie Jacobs <Amie.Jacobs@matsugov.us>; Katrina Kline <katrina.kline@matsugov.us>; MSB Farmers <MSB.Farmers@matsugov.us>; Permit Center <Permit.Center@matsugov.us>; Code Compliance <Code.Compliance@matsugov.us>; Planning <MSB.Planning@matsugov.us>; Alex Strawn <Alex.Strawn@matsugov.us>; Fred Wagner <Frederic.Wagner@matsugov.us>; Taunnie Boothby <Taunnie.Boothby@matsugov.us>; msbaddressing <msbaddressing@matsugov.us>; eric.r.schuler@usps.gov; John Aschenbrenner <John.Aschenbrenner@matsugov.us>; Andrew Fraiser <andrew.fraiser@enstarnaturalgas.com>; ROW <row@enstarnaturalgas.com>; Right of Way Dept.

<row@mtasolutions.com>; OSP Design Group <ospdesign@gci.com>; mearow@mea.coop; Peggy Horton

<Peggy.Horton@matsugov.us>; Rick Benedict <Rick.Benedict@matsugov.us>; Natasha Heindel

<Natasha.Heindel@matsugov.us> **Subject:** RFC Scorpion (MG)

Hello,

The following link is a request for comments for the proposed Scorpion Subdivision. Please ensure all comments have been submitted by February 3, 2025, so they can be incorporated into the staff report that will be presented to the Platting Officer.

Scorpion

Feel free to contact me if you have any questions.

Thank you,

Matthew Goddard Platting Technician 907-861-7881 Matthew.Goddard@matsugov.us

From:

Permit Center

Sent:

Wednesday, January 22, 2025 4:02 PM

To:

Matthew Goddard

Subject:

RE: RFC Scorpion (MG)

No comments from the Permit Center.

Brandon Tucker

Permit Technician

Matanuska-Susitna Borough Permit Center

350 E Dahlia Ave

Palmer AK 99645

P (907) 861-7871

F (907) 861-8158

From: Matthew Goddard < Matthew. Goddard @matsugov.us >

Sent: Wednesday, January 22, 2025 3:43 PM

To: Huling, Kristina N (DOT) < kristina.huling@alaska.gov>; Post, David E (DOT) < david.post@alaska.gov>; Kostelecky, Erica D (DOT) <erica.kostelecky@alaska.gov>; Myers, Sarah E E (DFG) <sarah.myers@alaska.gov>; Percy, Colton T (DFG) <colton.percy@alaska.gov>; regpagemaster@usace.army.mil; Tim Swezey <tim.swezey@mlccak.org>; psfisherak49@gmail.com; information@mlccak.org; Camden Yehle <camdenyehle@gmail.com>; lana@mtaonline.net; Michael Keenan < Michael Keenan@matsugov.us>; Jeffrey Anderson < Jeffrey. Anderson@matsugov.us>; Fire Code <Fire.Code@matsugov.us>; Brian Davis <Brian.Davis@matsugov.us>; Ron Bernier <Ron.Bernier@matsugov.us>; Land Management < Land. Management@matsugov.us>; Jillian Morrissey < Jillian. Morrissey@matsugov.us>; Tom Adams <Tom.Adams@matsugov.us>; Brad Sworts <Brad.Sworts@matsugov.us>; Jamie Taylor <Jamie.Taylor@matsugov.us>; Daniel Dahms < Daniel. Dahms@matsugov.us>; Tammy Simmons < Tammy. Simmons@matsugov.us>; Christina Sands <Christina.Sands@matsugov.us>; Amie Jacobs <Amie.Jacobs@matsugov.us>; Katrina Kline <katrina.kline@matsugov.us>; MSB Farmers <MSB.Farmers@matsugov.us>; Permit Center <Permit.Center@matsugov.us>; Code Compliance <Code.Compliance@matsugov.us>; Planning <MSB.Planning@matsugov.us>; Alex Strawn <Alex.Strawn@matsugov.us>; Fred Wagner <Frederic.Wagner@matsugov.us>; Taunnie Boothby <Taunnie.Boothby@matsugov.us>; msbaddressing <msbaddressing@matsugov.us>; eric.r.schuler@usps.gov; John Aschenbrenner <John.Aschenbrenner@matsugov.us>; Andrew Fraiser <andrew.fraiser@enstarnaturalgas.com>; ROW <row@enstarnaturalgas.com>; Right of Way Dept. <row@mtasolutions.com>; OSP Design Group <ospdesign@gci.com>; mearow@mea.coop; Peggy Horton <Peggy.Horton@matsugov.us>; Rick Benedict <Rick.Benedict@matsugov.us>; Natasha Heindel <Natasha.Heindel@matsugov.us>

Hello,

Subject: RFC Scorpion (MG)

The following link is a request for comments for the proposed Scorpion Subdivision.

Please ensure all comments have been submitted by February 3, 2025, so they can be incorporated into the staff report that will be presented to the Platting Officer.

Scorpion

Feel free to contact me if you have any questions.

From: Jeffrey Anderson

Sent: Friday, January 24, 2025 5:22 PM

To: **Platting**

RE: RFC Scorpion (MG) Subject:

It appears this proposal may affect a structure regulated by this office for conformity to Fire and Life Safety Standards as per AS 18.70.080.

Before beginning the construction, alteration, repair, or changing the occupancy of a building, substantial land structure, or structure regulated by the state division of fire and life safety, plans and specifications need to be submitted to this office. 13 AAC 50.027



JEFF ANDERSON

Assistant Chief / Fire Marshal CENTRAL MAT-SU FIRE DEPARTMENT Fire & Life Safety Division (907) 861-8383 FireCode@matsugov.us

From: Matthew Goddard < Matthew. Goddard @matsugov.us>

Sent: Wednesday, January 22, 2025 3:43 PM

To: Huling, Kristina N (DOT) <kristina.huling@alaska.gov>; Post, David E (DOT) <david.post@alaska.gov>; Kostelecky, Erica D (DOT) <erica.kostelecky@alaska.gov>; Myers, Sarah E E (DFG) <sarah.myers@alaska.gov>; Percy, Colton T (DFG) <colton.percy@alaska.gov>; regpagemaster@usace.army.mil; Tim Swezey <tim.swezey@mlccak.org>; psfisherak49@gmail.com; information@mlccak.org; Camden Yehle <camdenyehle@gmail.com>; lana@mtaonline.net; Michael Keenan < Michael. Keenan@matsugov.us>; Jeffrey Anderson < Jeffrey. Anderson@matsugov.us>; Fire Code <Fire.Code@matsugov.us>; Brian Davis <Brian.Davis@matsugov.us>; Ron Bernier <Ron.Bernier@matsugov.us>; Land Management < Land. Management@matsugov.us>; Jillian Morrissey < Jillian. Morrissey@matsugov.us>; Tom Adams <Tom.Adams@matsugov.us>; Brad Sworts <Brad.Sworts@matsugov.us>; Jamie Taylor <Jamie.Taylor@matsugov.us>; Daniel Dahms < Daniel. Dahms@matsugov.us>; Tammy Simmons < Tammy. Simmons@matsugov.us>; Christina Sands <Christina.Sands@matsugov.us>; Amie Jacobs <Amie.Jacobs@matsugov.us>; Katrina Kline

- <katrina.kline@matsugov.us>; MSB Farmers <MSB.Farmers@matsugov.us>; Permit Center
- <Permit.Center@matsugov.us>; Code Compliance <Code.Compliance@matsugov.us>; Planning
- <MSB.Planning@matsugov.us>; Alex Strawn <Alex.Strawn@matsugov.us>; Fred Wagner
- <Frederic.Wagner@matsugov.us>; Taunnie Boothby <Taunnie.Boothby@matsugov.us>; msbaddressing
- <msbaddressing@matsugov.us>; eric.r.schuler@usps.gov; John Aschenbrenner <John.Aschenbrenner@matsugov.us>;

Andrew Fraiser <andrew.fraiser@enstarnaturalgas.com>; ROW <row@enstarnaturalgas.com>; Right of Way Dept.

- <row@mtasolutions.com>; OSP Design Group <ospdesign@gci.com>; mearow@mea.coop; Peggy Horton
- <Peggy.Horton@matsugov.us>; Rick Benedict <Rick.Benedict@matsugov.us>; Natasha Heindel
- <Natasha.Heindel@matsugov.us>

Subject: RFC Scorpion (MG)

Hello,

The following link is a request for comments for the proposed Scorpion Subdivision.

Please ensure all comments have been submitted by February 3, 2025, so they can be incorporated into the staff report that will be presented to the Platting Officer.



ENSTAR Natural Gas Company, LLC

Engineering Department, Right of Way Section 401 E. International Airport Road P. O. Box 190288 Anchorage, Alaska 99519-0288 (907) 277-5551 FAX (907) 334-7798

January 27, 2025

Matanuska-Susitna Borough, Platting Division 350 East Dahlia Avenue Palmer, AK 99645-6488

To whom it may concern:

ENSTAR Natural Gas Company, LLC has reviewed abbreviated plat **SCORPION** (MSB Case # 2025-014) and advises that there is an existing ten feet (10FT) wide natural gas easement located within proposed Lot 1. Please show this 10FT wide natural gas easement as depicted on McCALLISTER SUBDIVISION LOTS 1A, 2A AND 3A, BLOCK 1, filed under Plat No. 2014-11, in the records of the Palmer Recording District, Third Judicial District, State of Alaska.


If you have any questions, please feel free to contact me at 334-7944 or by email at james.christopher@enstarnaturalgas.com.


Sincerely,


James Christopher Right Of Way Agent

James Christopher

ENSTAR Natural Gas Company, LLC







McCALLISTER INVESTMENT GROUP, LLC

SUBSCRIBED AND SWORN TO BEFORE ME THIS _____ DAY OF

MY COMMISSION EXPIRES NOTARY PUBLIC IN AND FOR ALASKA

1500 BOGARD ROAD

WASILLA, AK 99654

NOTARY'S ACKNOWLEDGMENT

______ 2024, for

4. EASEMENTS OF RECORD NOT SHOWN HEREON:

M.E.A. EASEMENT RECORDED JUNE 22, 1973 AT BOOK: 73, PAGE: 241

M.E.A. EASEMENT RECORDED SEPTEMBER 26, 1957 AT BOOK: 29, PAGE: 92

M.E.A. EASEMENT RECORDED JUNE 1, 2018 AT RECEPTION #2018-010927-0

e) M.E.A. EASEMENT RECORDED NOVEMBER 1, 2018 AT RECEPTION #2019-025015-0

WATER WELL AND ACCESS EASEMENT RECORDED FEBRUARY 05, 2018 AT RECEPTION #2018-002418-0

THAT I AM A REGISTERED PROFESSIONAL LAND SURVEYOR IN THE STATE OF ALASKA AND THAT THIS PLAT REPRESENTS A SURVEY MADE BY ME OR UNDER MY DIRECT SUPERVISION, AND THAT THE MONUMENTS SHOWN ON THE PLAT ACTUALLY EXIST AS DESCRIBED, AND THAT ALL DIMENSIONS AND OTHER DETAILS ARE TRUE AND CORRECT TO THE BEST OF MY KNOWLEDGE. DATED: _____

49th

DAN S. BUSH

PALMER RECORDING DISTRICT

THIRD JUDICIAL DISTRICT, STATE OF ALASKA

PREPARED BY:


BUSH CONSTRUCTION SURVEYS, INC.

MAILING: PO BOX 876390 WASILLA, AK 99687 PHYSICAL: 3167 COTTLE LOOP WASILLA, AK 99654

□FFICE# 907-373-6996

	Phone:	(907) 373-6996	Drawn: SH Scale: 10 - 50
Date:	3/29/2024	Date of Survey: FEBUARY 2024	Job# 23-12 MATT BROWN Field Bk.: N/A
License#: AECC729		CC729	SHEET Y OF 1

February 12, 2025 Abbre	eviated Plat Hearing Packet 86 of 116
	00 01 110



STAFF REVIEW AND RECOMMENDATIONS PUBLIC HEARING February 19, 2025

ABBREVIATED PLAT: ROWLAND FOREST RSB L/4-5

LEGAL DESCRIPTION: SEC 01, T17N, R02E, SEWARD MERIDIAN AK

PETITIONERS: MICK EWING

SURVEYOR/ENGINEER: RECON

ACRES: $6.76 \pm$ PARCELS: 2

REVIEWED BY: MATTHEW GODDARD CASE #: 2025-015

REQUEST: The request is to create two lots by adjusting the common lot line between Lots 4 & 5, Rowland Forest Subdivision, Plat No. 2019-20 to be known as **Lots 4A & 5A**, containing 6.76 acres +/-. The property is located west of N. Tranquility Lane, east of N. Smith Road, & north of E. Maud Road (Tax ID # 7837000L004 / L005); within the SW ¼ Section 01, Township 17 North, Range 02 East, Seward Meridian, Alaska. In the Butte Community Council and in Assembly District #1.

EXHIBITS

Vicinity Map and Aerial Photos

Soils Report

EXHIBIT A – 5 pgs

EXHIBIT B – 13 pgs

AGENCY COMMENTS

MSB DPW Pre-Design and Engineering Division MSB Development Services Utilities EXHIBIT C-2 pgs EXHIBIT D-2 pgs EXHIBIT E-2 pgs

<u>DISCUSSION</u>: The proposed subdivision creating two lots by adjusting the common lot line between Lots 4 & 5, Rowland Forest Subdivision, Plat No. 2019-20. Access for Lot 4A is from E. Browns Avenue, a Borough maintained road. Access for Lot 5A is from E. Maud Road, an ADOT&PF maintained road.

Soils Report: A geotechnical report was submitted (Exhibit B), pursuant to MSB 43.20.281(A). Steven Rowland, Registered Professional Engineer, notes that RECON, LLC completed an assessment of the subject property to determine compliance with MSB requirements for "usable area" as defined in Title 43 of Borough Code. In September 2024 and January 2025, Steve Rowland, PE completed an on-site property evaluation to verify that no change to the site conditions has occurred since the original subdivision site assessment was completed in 2018. In summary, Steve Rowland, PE, of RECON, LLC has reviewed the proposed lot line adjustment for Lots 4 & 5 of Rowland Forest Subdivision, topographic maps, geologic maps of the immediate area, and soils information of record and on adjacent properties. Based on the Subsurface investigation and the engineer's traverse of the property and familiarity with soils and geology of the subject area, it has been determined that each of the two proposed lots has the required minimum 10,000 square feet of "useable building area" and the required 10,000 contiguous square feet of "useable

septic area" as defined in MSB Title 43.20.281. There are no excessive slopes of significant extent that occur within the property, and there is no occurrence of surface water that impacts the proposed subdivision plan.

<u>As-Built and Topographic Mapping</u>: An as-built and topographic mapping information were submitted and are shown on the Agenda Plat. Based on the submitted as-built, no setback violations exist, nor will the proposed platting action create any violations.

Comments:

MSB DPW Pre-Design and Engineering Division (Exhibit C) has no comments.

MSB Permit Center (**Exhibit D**) notes that a driveway permit is required for the non-permitted access on Browns Avenue (**Recommendation #4**).

<u>Utilities</u>: (**Exhibit F**) ENSTAR has no comments or recommendations. GCI did not respond. MEA did not respond. MTA did not respond.

At the time of staff report write-up, there were no responses to the Request for Comments from ADF&G; USACE; Community Council #5 Butte; Fire Service Area #2 Butte; Road Service Area #26 Greater Butte; MSB Community Development, Emergency Services, Assessments, or Planning Division; GCI MEA or MTA.


CONCLUSION: The abbreviated plat of Rowland Forest RSB L/4-5 is consistent with AS 29.40.070 Platting Regulations and MSB 43.15.025 Abbreviated Plats. There were no objections from any federal or state agencies, Borough departments, or utilities. There were no objections to the plat from the public in response to the Notice of Public Hearing. Legal and physical access exists to the proposed lots, consistent with MSB 43.20.100 Access Required, MSB 43.20.120 Legal Access and MSB 43.20.140 Physical Access. Frontage for the subdivision exists, pursuant to MSB 43.20.320 Frontage. A soils report was submitted, pursuant to MSB 43.20.281(A)(1).


FINDINGS OF FACT


- 1. The plat of Rowland Forest RSB L/4-5 is consistent with AS 29.40.070 Platting Regulations and MSB 43.15.025 Abbreviated Plats.
- 2. A soils report was submitted, pursuant to MSB 43.20.281(A)(1).
- 3. All lots will have legal and physical access consistent with MSB 43.20.100, MSB 43.20.120 and MSB 43.20.140.
- 4. Each lot has the required frontage pursuant to MSB 43.20.320.
- 5. At the time of staff report write-up, there were no responses to the Request for Comments from ADF&G; USACE; Community Council #5 Butte; Fire Service Area #2 Butte; Road Service Area #26 Greater Butte; MSB Community Development, Emergency Services, Assessments, or Planning Division; GCI MEA or MTA.
- 6. There were no objections from any federal or state agencies, or Borough departments.
- 7. There were no objections from the public in response to the Notice of Public Hearing.


<u>RECOMMENDATIONS OF CONDITIONS OF APPROVAL</u> for the abbreviated plat of Rowland Forest RSB L/4-5, Section 01, Township 17 North, Range 02 East, Seward Meridian, Alaska, contingent on staff recommendations:

- 1. Taxes and special assessments must be paid in full for the year of recording, pursuant to MSB 43.15.053(F) and AS 40.15.020. Pay taxes and special assessments (LIDs), by CERTIFIED FUNDS OR CASH.
- 2. Provide updated Certificate to Plat executed within seven (7) days of recording of plat and submit Beneficiary Affidavit for any holders of a beneficial interest.
- 3. Pay postage and advertising fees.
- 4. Apply for driveway permits for all non-permitted accesses. Provide platting staff a copy of all driveway permits/permit applications.
- 5. Show all easements of record on final plat.
- 6. Submit recording fees, payable to Department of Natural Resources (DNR).
- 7. Submit final plat in full compliance with Title 43.













565 West Recon Circle, · Palmer, Alaska 99645 907.746.3630 steve@reconllc.net

Matanuska-Susitna Borough Platting Division 350 East Dahlia St. Palmer, Alaska 99645



January 10, 2025

Re:

Soils Investigation Report for: Rowland Forest Subdivision, Lots 4 & 5,

Within the SW1/4, SW1/4, Section 1, T 17 N, R 2 E, Seward Meridian, Alaska

Attn: Platting Officer

Introduction

RECON, LLC has completed an assessment of the subject property to determine compliance with MSB requirements for "usable area" as defined in Title 43 of Borough Code. The intent of this plat is to simply adjust the single lot line that is common to Lot 4 and Lot 5 of Rowland Forest Subdivision. Currently, Lot 4 has an area of 4.0 acres and will be decreased in size to 2.5 acres. Lot 5 currently has an area of 2.75 acres and will be increased in size to 4.25 acres. Each of the lots is undeveloped and fully forested. Lot 4 fronts on E Browns Avenue, and Lot 5 fronts on E Maud Road. The proposed lot line adjustment is shown in the referenced preliminary plat of Rowland Forest Subdivision.

For the original creation of Rowland Forest Subdivision, completed in 2018, RECON, LLC prepared the Soils Investigation Report and usable area assessment. A copy of that report is included with this report as 'Attachment A'. The 2018 investigation included a test pit on each of the 6 lots included in that platting effort.

Field Investigation

In September 2024 and January 2025, Steve Rowland, PE completed an on-site property evaluation to verify that no change to site conditions has occurred since the original subdivision site assessment was completed in 2018 (reference Attachment A)

Summary & Conclusions

In summary, Steve Rowland, PE, of RECON, LLC has reviewed the proposed lot line adjustment for Lots 4 & 5 of Rowland Forest Subdivision, topographic maps, geologic maps of the immediate area, and soils information of record and on adjacent properties. Based on the subsurface investigation and the engineer's traverse of the property and familiarity with soils and geology of the subject area, it has been determined that each of the two proposed lots has the required minimum 10,000 square feet of "useable building area" and the required 10,000 contiguous square feet of "useable septic area" as defined in MSB Title 43.20.281. There are no excessive slopes of significant extent that occur within the property, and there is no occurrence of surface water that impacts the proposed subdivision plan.



565 West Recon Circle, - Paliner, Alaska 99645 907.746.3630 steve@reconlk.net

This plat is simply to complete a lot line adjustment and there is not road development or site work of any kind required.

Sincerely,

Steven R. Rowland, PE



ADDA

Attachment A: Soils Investigation Report for: Rowland Forest Subdivision, a replat of Eckert Subdivision No, 2, Lots 9A-1 and 9A-4, (11 pages)



481 West Recon Circle, · Palmer, Alaska 99645 907.746.3630 · 907.355.3006 cell · steve@reconllc.net

August 16, 2018

Matanuska-Susitna Borough Platting Division 350 East Dahlia St. Palmer, Alaska 99645

Re: Soils Investigation Report for: Rowland Forest Subdivision, a replat of Eckert

Subdivision No, 2, Lots 9A-1 and 9A-4, Within SW1/4, SW1/4, Section 1, T 17 N, R 2

Previous Soils Report

E, Seward Meridian, Alaska

(MSB Account Nos. 5703000L009A-1 and 5703000L009A-4)

Attn: Platting Officer

Introduction

RECON, LLC has completed an assessment of the subject property to determine compliance with MSB requirements for "usable area" as defined in Title 43 of Borough Code. The subject parent parcels, being 2.50 acres and 20.24 acres, are to be divided to create 6 lots, with areas ranging from 2.50 to 6.74 acres. The parent 20.24-acre parcel (Lot 9A-4) is occupied by a single-family residence that will be wholly contained within the proposed Lot 3. Proposed Lot 4 fronts on E. Browns Avenue, while the remaining five lots front on E. Maud Road. The proposed lots and existing development are shown in the referenced preliminary plat of Rowland Forest Subdivision prepared by RECON, LLC. Included as Attachment A is a project area map showing the generalized subdivision layout and location of test pits.

On June 16, 2018, Steve Rowland, PE completed an on-site property evaluation and soils investigation sufficient to provide an assessment of suitability for subdivision of the subject property. One test pit was dug on each of the following proposed lots: 1, 2, 3, 5, & 6. Locations of the test pits were determined to be representative of conditions found on each lot. A Test Pit was also completed on Lot 4 by Mr. Rowland, during an earlier subdivision of the property. The log for that test pit has been incorporated with this report. Included as Attachment B are the test pit logs for each lot.

Project Area Description

Regionally, the subject property is located on an ancient alluvial fan consisting of layered and interbedded well- to poorly-graded sand, gravel, and silt deposits overlain by a thin blanket of wind-deposited silt (loess) and fine sand. The soils are typically excellent for this type of development. Groundwater can be expected at depths in excess of 70 ft. The author has completed numerous soil test pits in the area of the subject subdivision and has never encountered groundwater within the depth of excavation. Bedrock has been reported on area well logs at depths from 100 ft to 150 ft. The entire property slopes gently to the southwest at gradients of 2 to 3 percent. Ground surface elevation is varies from 200 ft to 235 ft above mean



481 West Recon Circle, Palmer, Alaska 99645 907.746.3630 · 907.355.3006 cell · steve@reconllc.net

sea level, with the highest point being at the northeast corner of the property. Area drainage is excellent, given natural ground slope and developed ditches along E. Maud Road and E. Browns Ave. There are no active drainage ways or streams within the subject property. Any future residential development can be accomplished without adversely affecting area drainage patterns or adjacent properties. The subject property is lightly developed with one typical single-family residence located in the center of the 20.24 acre parent parcel. All undeveloped area is forested with a mixed stand of mature birch and white spruce. Access to the subject property is via E. Browns Avenue for proposed Lot 4, and via E. Maud Road for the remaining proposed lots. All proposed lots front along the same street as their respective access. E. Browns Avenue is Borough-maintained, E. Maud Road is State-maintained and has recently been upgraded and paved to meet residential collector road standards. The residence located on proposed Lot 3, and homes located on adjacent properties, utilize on-site wells and conventional wastewater disposal systems. Surrounding properties are mostly developed with single-family homes on 1-acre to 2.5 acre lots. All lots are rectilinear with ratios essentially ranging from 2:1 to 3:2. Proposed Lots 2 & 5 are rectilinear at a roughly 3:2 ratio and includes a 60 ft by approximately 420 ft appendage extending to the south, providing frontage on E. Maud Road. The appendage for proposed Lots 2 & 5 extend from the southeast and southwest corners, respectively.

Field Investigation

On June 15, 2018, 5 test pits were excavated on the subject property at locations shown on the map in Attachment A. Test Pits 3 through 7 were selected as representative of the conditions to be expected throughout proposed subdivision. Each test pit was logged by Steve Rowland, PE, of RECON, LLC. Additional test pits were excavated as part of the process for subdividing Lot 9A, Eckert Subdivision No. 2, recorded in Plat 2005-62, Palmer Recording District. These pits were also completed by RECON, LLC on October 15, 2004 and were located within existing Lot 9A-3, Eckert Subdivision No. 2, an adjacent lot to the proposed Rowland Forest Subdivision (Test Pit 1), and within the proposed Lot 4 (Test Pit 2).

Soils Description

Soils observed included a surface layer of fine sandy silt overlying sandy gravel with few cobbles and included strata or lenses of fine gravel, sand, or silt. The silt (topsoil) layer was found to be of variable thickness and the sandy gravel extended to the limit of the test pit at a depth of 12 - 12.2 ft. In Test Pit 4, there was a layer of stratified silt and sand below the gravelly sand to 10.5 ft, returning to gravelly sand to the bottom of the test pit at 12 ft. The gravel soils have moderately rapid to rapid permeability and are conducive to the type of development planned. No groundwater was encountered at the time test pits were excavated and logged. Refer to Attachment B, "Geologic Log of Test Pits."

Summary & Conclusions

In summary, Steve Rowland, PE, of RECON, LLC has reviewed the proposed subdivision plan, topographic maps, geologic maps of the immediate area, and soils information of record and on adjacent properties. Based on the subsurface investigation and the engineer's traverse of the



481 West Recon Circle, · Palmer, Alaska 99645 907.746.3630 · 907.355.3006 cell · steve@reconllc.net

property and familiarity with soils and geology of the subject area, it has been determined that each of the six proposed lots has the required minimum 20,000 square feet of "useable building area" and the required 10,000 square feet of "useable septic area" as defined in MSB Title 43. There are no excessive slopes of significant extent that occur within the property, and there is no significant occurrence of surface water that impacts the proposed subdivision plan.

Sincerely,


Steven R. Rowland, PE

OF A/
Sleven R. Sowland
CE-7241

AGESSON

Attachment A: Subdivision Plan and Test Pit Location Map (1 page)

Attachment B: Test Pit Logs (6 pages)



Attachment B Test Pit Logs 6 Pages

February 12, 2025 Abbreviated Plat Hearing Packet GEOLOGIC LOG TEST PIT: **TP - 2** Interval Sample Method Number Interval Foot Feet Ground Flev.: NA Vegetation: Birch & Location: Total Depth : 13.5 White Spruce Near center of NE lot per Bottom Elev.: Remarks: NA _ (Parcel 9A-1) Sample Sample Collar Elev.: Densely forested NA with trees to 18"dbh Reference: NA 0 0.0 - 0.5Organic material (moss and forest litter) 1 0.5 - 1.52 Silt grading to fine sandy Silt, It. brown to tan, soft, moist. (ML) 3 4 1.5 - 10.0' Stratified gravelly Sand, Sand, Silt and fine sandy silt, 5 clasts subangular to subrounded with max. dia. of 1.5", silt strata show some mottling, tan to olive, firm to 6 moderately dense, dry to moist. (SP.SM.ML) 7 G 1 8 9 10 1 10.0 - 13.5' Sandy Gravel with few cobbles, olive, moderately dense, 2 dry, clasts subangular to subrounded. 3 4 13.5 TD 5 No groundwater encountered 6 Average soil permeability is "good" 7 Note: Terrain is essentially flat with approximately 3% 8 Slope to the southwest. 9 20 1 2 3 4 5 6 7 8 9 30

RECON, LLC

Rowland Engineering Consultants

481 W. Arctic Ave. Palmer, Alaska 99645 Ph: (907) 746-3630

Project No.: Project Name: _

Location: Method Used: Engineer: Date Begun:

0410

Sheet 1 of 2 Log #TP-2 Subsivision of Lot 9A, Eckert Subdivision No.2

Palmer, AK Brown's Drive

Hydraulic Excavator Steve Rowland, P.E. October 15, 2004

Rig Type: Hitachi EX100 Contractor: Recon. LLC Date Comp.: same

GEOLOGIC LOG TEST PIT: TP-3 Number Ground Elev.: 210.5' Total Depth : 12.2' Bottom Elev.: 198.3' Vegetation: Birch & Location: White Spruce North end of Lot 2 Remarks: Densely forested w/ trees to 18" dbh Collar Elev.: N/A N:2773373 Sample E: 1810407 Reference: Coord.: AKSP Z4 NAD83 0 0.0' - 0.5' 0.5' - 3.0' Organic mat, brown, very soft Silt grading to Silt & silty Sand brown to tan, soft, moist (ML/SM) 2 3 3.0' - 10.5 gravelly Sand. Coarse, moderately dense, dry few/thin lenses of gravel w/ silt (SW/GM) 5 6 7 8 9 10 10.5' - 12.2'Silt w/ trace Gravel & Sand, tan, w/ light mottling 1 firm, moist (ML) 2 No groundwater encountered 12.2 3 Average soil permeability is "good" 4 Note: Terrain is essentially flat with approximately 2% 5 slope to the southwest 6 7 8 9 20 1 2 3 4 5 6

RECON, LLC

7 8

30

Rowland Engineering Consultants

481 W. Recon Cir. Palmer, Alaska 99645 Ph: (907) 746-3630

Project No.:

2018-105

Sheet 1 of 1 Log #TP-3

Location:

Project Name: Rowland Forest Subd.

Steve Rowland, P.E.

16-Jun-2018

17001 E Maud Rd Palmer, AK Method Used: Hydraulic Excavator

Rig Type: <u>Kubota 55</u> Contractor: <u>RECON, LLC</u> Date Comp.: SAME

Engineer: Date Begun:

GEOLOGIC LOG TEST PIT: TP-4

Interval Interval Foot Method per 드 Sample Sample Graphic Sample

Ground Elev.: 217.5' Total Depth: 12.0 Bottom Elev.: 205.5 Collar Elev.: N/A


Reference:

Vegetation: Birch & White Spruce Remarks:

Densely forested w/ trees to 18" dbh


Location: North center of Lot 3 N:2773336 E: 1810752

Coord.: AKSP Z4 NAD83



5

0.0' - 0.5' 0.5' - 4.0'	Organic mat, brown, very soft Silt w/ some sandy layers brown to tan, soft, moist (ML/SM)
4.0' - 5.5'	gravelly Sand, coarse, brown, moderately dense, dry (SW) few/thin lenses of Gravel w/ Silt (SW/GM)
5.5' - 10.5'	Silt & Sand, stratified, tan to olive firm/moderately dense, dry to moist (SP, SM, ML)
10.5' - 12.0'	gravelly Sand, olive, moderately dense, dry, (SP)
	No groundwater encountered
	Average soil permeability is "good"
	Note: Terrain is essentially flat with approximately 2%



RECON, LLC

Rowland Engineering Consultants

481 W. Recon Cir. Palmer, Alaska 99645 Ph: (907) 746-3630

Project No.:

2018-105

16-Jun-2018

Project Name: Rowland Forest Subd.

Location: Engineer: Date Begun:

17001 E Maud Rd Method Used: Hydraulic Excavator Steve Rowland, P.E.

Palmer, AK

Rig Type: Kubota 55 Contractor: RECON, LLC Date Comp.: SAME

Sheet 1 of 1 Log #TP-4

GEOLOGIC LOG TEST PIT: TP-5

Interval Number Method per Sample Sample Sample Graphic


Ground Elev.: 221.0' Total Depth : 12.1' Bottom Elev.: 208.9

Collar Elev.: N/A Reference:

Vegetation: Birch & White Spruce Remarks:

Densely forested w/ trees to 18" dbh

Location: North end of Lot 5 N:2773242 E: 1811077 Coord.: AKSP Z4 NAD83



0.0' - 0.5' 0.5' - 3.0'	Organic mat, brown, very soft, dry Silt grading to sandy Silt & Sand (ML/SM)
3.0' - 4.8'	gravelly Sand, coarse, brown, moderately dense, dry (SW)
4.8' - 6.0'	Silt, tan to brown, firm, moist, (ML)
6.0' - 8.5'	Gravel w/ thin Silt & silty Sand layers gray, rusty brown, tan, (GP, ML, SM)
8.5' - 12.1'	sandy Gravel, olive, moderately dense, dry, (GW)
31	No groundwater encountered
	Average soil permeability is "good"
	Note: Terrain is essentially flat with approximately 2% slope to the southwest



RECON, LLC

Rowland Engineering Consultants

481 W. Recon Cir. Palmer, Alaska 99645 Ph: (907) 746-3630

Project No.:

2018-105

Sheet 1 of 1 Log #TP-5

Engineer:

Project Name: Rowland Forest Subd. Location: 17001 E Maud Rd Palmer, AK Method Used: Hydraulic Excavator Steve Rowland, P.E. Date Begun: 16-Jun-2018

Rig Type: Kubota 55 Contractor: RECON, LLC Date Comp.: SAME

GEOLOGIC LOG TEST PIT: TP-6

Number Interval Sample Method Log per 드 Graphic Sample Sample Depth

Ground Elev.: 203.5' Total Depth : 12.0' Bottom Elev.: 191.5

Collar Elev.: N/A Reference:

Vegetation: Birch &

White Spruce Remarks:


Densely forested w/ trees to 18" dbh

Location:

Center of Lot 1

N:2772770 E: 1810368

Coord.: AKSP Z4 NAD83



	00014 711.01 21 111.200
0.0' - 0.5' 0.5' - 3.0'	Organic mat, brown, very soft, dry Silt grading to Silt & Sand stratified
	brown to tan, soft to firm, dry (ML, SP)
3.0' - 4.8'	Stratified Silt & Sand, tan to brown, firm to moderately dense moist to dry, (SP, ML)
4.8' - 6.2'	Sand w/ thin layers of Silt, gray to brown, dry (SP, ML)
6.2' - 12.0'	Coarse sandy Grave! w/ lenses of Silt, gray to brown, dry (SP, ML)
	No groundwater encountered
	Average soil permeability is "good"
	Note: Terrain is essentially flat with approximately 2%
	slope to the southwest



RECON, LLC

8 9 30

Rowland Engineering Consultants

481 W. Recon Cir. Palmer, Alaska 99645 Ph: (907) 746-3630

Project No.: Project Name: Rowland Forest Subd.

2018-105

Palmer, AK

Sheet 1 of 1 Log # TP - 6

Location: Engineer: Date Begun:

17001 E Maud Rd Method Used: Hydraulic Excavator Steve Rowland, P.E.

16-Jun-2018

Rig Type: <u>Kubota 55</u> Contractor: RECON, LLC Date Comp.: SAME

GEOLOGIC LOG TP-TEST PIT:

Foot Method Number Log 드 Sample Sample Sample

Ground Elev.: 216.5'
Total Depth: 12.0'
Bottom Elev.: 204.5'

Collar Elev.: N/A Reference: N/A

Vegetation: Birch & White Spruce

Remarks:


Densely forested w/ trees to 18" dbh

Location:

North center of Lot 6

N:2772921 E: 1811106

Coord.: AKSP Z4 NAD83



0.0' - 0.5' 0.5' - 2.8'	Organic mat, brown, very soft, dry Silt & silty fine Sand, tan, soft, moist (ML)
2.8' - 5.6'	gravelly Sand, coarse, dry, tan to brown moderately dense (SW)
5.6' - 8.0'	Silt w/ some Sand, brown to tan, firm, moist (ML, SM)
8.0' - 9.5'	gravelly Sand, coarse, dry, moderately dense (SW)
9.5' - 12.0'	Silt w/ trace Sand, tan, light mottling, hint of organic material, firm, dry to moist (ML)
	No groundwater encountered Average soil permeability is "good"
	Note: Terrain is essentially flat with approximately 2% slope to the southwest



RECON, LLC

Rowland Engineering Consultants

481 W. Recon Cir. Palmer, Alaska 99645 Ph: (907) 746-3630

Project No.:

Location:

2018-105

Project Name: Rowland Forest Subd.

Engineer: Date Begun:

Palmer, AK 17001 E Maud Rd Method Used: Hydraulic Excavator Steve Rowland, P.E. 16-Jun-2018

Sheet 1 of 1 Log #TP-7 Rig Type: Kubota 55

Contractor: RECON, LLC Date Comp.: SAME

From:

Jamie Taylor

Sent:

Wednesday, February 5, 2025 2:45 PM

To:

Matthew Goddard; Pre-Design & Engineering

Cc:

Tammy Simmons; Daniel Dahms

Subject:

Re: RFC Rowland Forest RSB (MG)

My bad, I was thinking this was a little farther east off the Pioneer standard section of Browns Avenue. No comments from PD&E on this one.

Jamie Taylor, PE (she/her) Civil Engineer Matanuska-Susitna Borough Department of Public Works

t: 907-861-7765 c: 907-355-9810

jamie.taylor@matsugov.us http://www.matsugov.us/

From: Matthew Goddard < Matthew. Goddard @ matsugov.us >

Sent: Wednesday, February 5, 2025 1:41 PM

To: Pre-Design & Engineering <pde@matsugov.us>

Cc: Jamie Taylor < Jamie. Taylor@matsugov.us>; Tammy Simmons < Tammy. Simmons@matsugov.us>; Daniel Dahms

<Daniel.Dahms@matsugov.us>

Subject: RE: RFC Rowland Forest RSB (MG)

Good afternoon,

I am preparing the staff report for Rowland Forest RSB and have a question on your comment. Currently the property fronts on E. Browns Avenue and E. Maud Road. Both roads are certified and maintained, is this comment meant to be for another case?

If you could let me know it would be appreciated.

Thank you, Matthew Goddard Platting Technician 907-861-7881

Matthew.Goddard@matsugov.us

From: Pre-Design & Engineering <pde@matsugov.us>

Sent: Friday, January 31, 2025 2:49 PM

To: Matthew Goddard < Matthew. Goddard@matsugov.us>

Cc: Brad Sworts <Brad.Sworts@matsugov.us>; Jamie Taylor <Jamie.Taylor@matsugov.us>; Tammy Simmons

<Tammy.Simmons@matsugov.us>; Daniel Dahms <Daniel.Dahms@matsugov.us>

Subject: RE: RFC Rowland Forest RSB (MG)

Matthew.

Per 43.20.100 (F)(2)(a), A note shall be placed on the plat to state that if any of the lots or parcels are further subdivided which would create more than the original lots created, a road must be constructed to minimum residential standards to provide physical access to the lots being further subdivided.

PD&E

From: Matthew Goddard < Matthew. Goddard @matsugov.us >

Sent: Wednesday, January 22, 2025 4:34 PM

To: Myers, Sarah E E (DFG) < sarah.myers@alaska.gov >; Percy, Colton T (DFG) < colton.percy@alaska.gov >;

regpagemaster@usace.army.mil; butteakcc@gmail.com; Michael Shipton < Michael.Shipton@matsugov.us >; Brian Davis

< Brian. Davis@matsugov.us >; meshie@mtaonline.net; timhaledistrict1@gmail.com; Land Management

<<u>Land.Management@matsugov.us</u>>; Jillian Morrissey <<u>Jillian.Morrissey@matsugov.us</u>>; Tom Adams

<<u>Tom.Adams@matsugov.us</u>>; Permit Center <<u>Permit.Center@matsugov.us</u>>; Code Compliance

<Code.Compliance@matsugov.us>; Brad Sworts <Brad.Sworts@matsugov.us>; Jamie Taylor

<Jamie.Taylor@matsugov.us>; Daniel Dahms <Daniel.Dahms@matsugov.us>; Tammy Simmons

<<u>Tammy.Simmons@matsugov.us</u>>; Christina Sands <<u>Christina.Sands@matsugov.us</u>>; Amie Jacobs

>> Katrina Kline <a href="mailto:MS

Planning < MSB.Planning@matsugov.us>; Alex Strawn < Alex.Strawn@matsugov.us>; Fred Wagner

< Frederic. Wagner@matsugov.us>; Taunnie Boothby < Taunnie. Boothby@matsugov.us>; msbaddressing

<msbaddressing@matsugov.us>; eric.r.schuler@usps.gov; John Aschenbrenner <John.Aschenbrenner@matsugov.us>;

Andrew Fraiser < andrew.fraiser@enstarnaturalgas.com >; ROW < row@enstarnaturalgas.com >; Right of Way Dept.

<row@mtasolutions.com>; OSP Design Group <ospdesign@gci.com>; mearow@mea.coop

Subject: RFC Rowland Forest RSB (MG)

Hello,

The following link is a request for comments for the proposed Rowland Forest RSB L/4-5. Please ensure all comments have been submitted by February 3, 2025, so they can be incorporated in the staff report that will be presented to the Platting Officer.

Rowland Forest RSB L4-5

Feel free to contact me if you have any questions.

Thank you,

Matthew Goddard
Platting Technician
907-861-7881
Matthew.Goddard@matsugov.us

From:

Permit Center

Sent:

Thursday, January 23, 2025 8:22 AM

To:

Matthew Goddard

Subject: Attachments: RE: RFC Rowland Forest RSB (MG)

Screenshot 2025-01-23 082050.png

Thank you sir. They'll need a DW permit as shown.

Brandon Tucker

Permit Technician

Matanuska-Susitna Borough Permit Center

350 E Dahlia Ave

Palmer AK 99645 P (907) 861-7871

F (907) 861-8158

From: Matthew Goddard < Matthew. Goddard @ matsugov.us >

Sent: Wednesday, January 22, 2025 4:34 PM

To: Myers, Sarah E E (DFG) <sarah.myers@alaska.gov>; Percy, Colton T (DFG) <colton.percy@alaska.gov>;

regpagemaster@usace.army.mil; butteakcc@gmail.com; Michael Shipton < Michael.Shipton@matsugov.us>; Brian Davis

<Brian.Davis@matsugov.us>; meshie@mtaonline.net; timhaledistrict1@gmail.com; Land Management

<Land.Management@matsugov.us>; Jillian Morrissey <Jillian.Morrissey@matsugov.us>; Tom Adams

<Tom.Adams@matsugov.us>; Permit Center <Permit.Center@matsugov.us>; Code Compliance

<Code.Compliance@matsugov.us>; Brad Sworts <Brad.Sworts@matsugov.us>; Jamie Taylor

<Jamie.Taylor@matsugov.us>; Daniel Dahms <Daniel.Dahms@matsugov.us>; Tammy Simmons

<Tammy.Simmons@matsugov.us>; Christina Sands <Christina.Sands@matsugov.us>; Amie Jacobs

<Amie.Jacobs@matsugov.us>; Katrina Kline <katrina.kline@matsugov.us>; MSB Farmers <MSB.Farmers@matsugov.us>;

Planning <MSB.Planning@matsugov.us>; Alex Strawn <Alex.Strawn@matsugov.us>; Fred Wagner

<Frederic.Wagner@matsugov.us>; Taunnie Boothby <Taunnie.Boothby@matsugov.us>; msbaddressing

<msbaddressing@matsugov.us>; eric.r.schuler@usps.gov; John Aschenbrenner <John.Aschenbrenner@matsugov.us>;

Andrew Fraiser <andrew.fraiser@enstarnaturalgas.com>; ROW <row@enstarnaturalgas.com>; Right of Way Dept.

<row@mtasolutions.com>; OSP Design Group <ospdesign@gci.com>; mearow@mea.coop

Subject: RFC Rowland Forest RSB (MG)

Hello,

The following link is a request for comments for the proposed Rowland Forest RSB L/4-5.


Please ensure all comments have been submitted by February 3, 2025, so they can be incorporated in the staff report that will be presented to the Platting Officer.

Rowland Forest RSB L4-5

Feel free to contact me if you have any questions.

Thank you,

Matthew Goddard Platting Technician





ENSTAR Natural Gas Company, LLC

Engineering Department, Right of Way Section 401 E. International Airport Road P. O. Box 190288 Anchorage, Alaska 99519-0288 (907) 277-5551 FAX (907) 334-7798

January 27, 2025

Matanuska-Susitna Borough, Platting Division 350 East Dahlia Avenue Palmer, AK 99645-6488

To whom it may concern:

ENSTAR Natural Gas Company, LLC has reviewed the following preliminary plat and has no comments or recommendations.

• ROWLAND FOREST SUBD. LOTS 4A & 5A (MSB Case # 2025-015)


If you have any questions, please feel free to contact me at 334-7944 or by email at james.christopher@enstarnaturalgas.com.


Sincerely,

James Christopher

Right of Way & Compliance Agent ENSTAR Natural Gas Company, LLC

James Christopher





1/10/2025 1:01 PM